

ESTIMATE TO REPAIR

VEHICLE NO. : GBA 4105 B
MAKE : TOYOTA
MODEL : HIACE MANUAL
YEAR : 2007
CHASSIS NO : JTFHT02P600004498

SURVEYOR NAME : *Kenneth Choke*
DATE OF SURVEY : *22.07.20*
TIME OF SURVEY :

DATE : 19-Jun-20
DATE OF ACCIDENT : 17-Jun-20
THIRD PARTY REF : GBG 5111 U
THIRD PARTY REF : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper <i>496.30</i>				\$ <i>568.10</i>
1 pc	front bumper reinforcement				\$ <i>296.80</i>
2 pcs	front bumper retainer				\$ <i>168.00</i>
10 pcs	front bumper clips		\$ 84.00		\$ <i>50.00</i>
1 pc	front grille <i>624.70</i>		\$ 5.00		\$ <i>843.00</i>
2 pcs	head lamps <i>789.50</i>				\$ <i>1,794.80</i>
1 pc	bonnet <i>757</i>	<i>1/15 Thg.m</i>	\$ 897.40	<i>0/15m x</i>	\$ <i>967.44</i>
1 pc	bonnet lock				\$ <i>89.00</i>
1 pc	bonnet emblem				\$ <i>59.00</i>
1 pc	front support panel				\$ <i>324.00</i>
1 pc	air-con condenser				\$ <i>1,430.00</i>
	Less 25%				\$ <i>6,590.14</i>
					\$ <i>1,647.54</i>
					\$ <i>4,942.61</i>
1 pc	front number plate	S.Nett			\$ <i>40.00</i>
1 pc	DHL logo	S.Nett			\$ <i>300.00</i>
	To putty & spray paint				\$ <i>480.00</i>
	To check front wiring & focus head lights.				\$ <i>30.00</i>
	To replace aircon condenser vacuum and refill gas.				\$ <i>80.00</i>
	Labour charges				\$ <i>600.00</i>
TG/VL	TOTAL				\$ <i>6,472.61</i>

*Not Notified
L1 Rep & 3300k
Repairing After Paint
4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Lim Tan Motor Pte Ltd
Bik 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575821
Tel: 65-64520893 Fax: 65-64589127 Email: *edmund@lmt.sg*
Co. Reg No. 199307277D GST Reg No. M2-0010086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd