



ESTIMATE TO REPAIR

VEHICLE NO. : GBA 4105 B
 MAKE : TOYOTA
 MODEL : HIACE MANUAL
 YEAR : 2007
 CHASSIS NO : JTFHT02P600004488

SURVEYOR NAME : *Kenneth Chik*
 DATE OF SURVEY : *22.04.20*
 TIME OF SURVEY :

DATE : 19-Jun-20
 DATE OF ACCIDENT : 17-Jun-20
 THIRD PARTY REF : GSG 5111 U

CHINA TAPING INSURANCE (SINGAPORE) PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper				\$ 568.10
1 pc	front bumper reinforcement				\$ 298.80
2 pcs	front bumper retainer		\$ 84.00		\$ 168.00
10 pcs	front bumper clips		\$ 5.00		\$ 50.00
1 pc	front grille				\$ 843.00
2 pcs	head lamps				\$ 1,794.80
1 pc	bonnet		\$ 897.40		\$ 897.44
1 pc	bonnet lock				\$ 89.00
1 pc	bonnet emblem				\$ 59.00
1 pc	front support panel				\$ 324.00
1 pc	air-con condenser				\$ 1,430.00
	Less 25%				\$ 6,590.14
					\$ 1,647.54
					\$ 4,942.61
1 pc	front number plate	S.Nett			\$ 40.00
1 pc	DHL logo	S.Nett			\$ 300.00
	To putty & spray paint				\$ 480.00
	To check front wiring & focus head lights.				\$ 30.00
	To replace aircon condenser vacuum and refill gas.				\$ 80.00
	Labour charges				\$ 600.00
TG/VL	TOTAL				\$ 6,472.61

*Not available
 1 Day &
 Repair After Paint
 3-4 days*

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplemental claim(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Lim Tan Motor Pte Ltd
 116-118 Ming Drive #02-02 Sin Ming Industrial Building Singapore 570011
 Tel: 65-64298900 Fax: 65-64298927 Email: enquiry@ltdm.com.sg
 Co. Reg No. 1972770 GST Reg No. 400000000

This document must not be reproduced, in whole or in part, or transmitted to third party or parties without prior written consent of Lim Tan Motor Pte Ltd