

ESTIMATE TO REPAIR

VEHICLE NO. : GBA 4105 B
 MAKE : TOYOTA
 MODEL : HIACE MANUAL
 YEAR : 2007
 CHASSIS NO : JTFHT02P600004498

SURVEYOR NAME :
 DATE OF SURVEY :
 TIME OF SURVEY :

DATE : 19-Jun-20
 DATE OF ACCIDENT : 17-Jun-20
 THIRD PARTY REF : GBG 5111 U
 THIRD PARTY REF : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper				\$ 568.10
1 pc	front bumper reinforcement				\$ 296.80
2 pcs	front bumper retainer		\$ 84.00		\$ 168.00
10 pcs	front bumper clips		\$ 5.00		\$ 50.00
1 pc	front grille				\$ 843.00
2 pcs	head lamps		\$ 897.40		\$ 1,794.80
1 pc	bonnet				\$ 967.44
1 pc	bonnet lock				\$ 89.00
1 pc	bonnet emblem				\$ 59.00
1 pc	front support panel				\$ 324.00
1 pc	air-con condenser				\$ 1,430.00
	Less 25%				\$ 6,590.14
					\$ 1,647.54
					\$ 4,942.61
1 pc	front number plate	S.Nett			\$ 40.00
1 pc	DHL logo	S.Nett			\$ 300.00
	To putty & spray paint				\$ 480.00
	To check front wiring & focus head lights.				\$ 30.00
	To replace aircon condenser vacuum and refill gas.				\$ 80.00
	Labour charges				\$ 600.00
TG/VL	TOTAL				\$ 6,472.61

Lim Tan Motor Pte Ltd
 Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg
 Co. Reg No. 199307277D GST Reg No. M2-0019088-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd