

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4 / FC120006484 / UKS3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / R/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt & O/S Body
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) __S + RS __SI

) Photos

) Others

TOTAL

15/8/20 4/5 3000 confirmed with MR Teo

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

First

Owner : Lim Yong Tat

Accident Date : 12-Jun-20

Vehicle No : JTX716

Vehicle Model : Yamaha Xmax

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fork assy	Self \$/7m 980.00 2
1	Fork under bracket cover	\$ Self 190.00 2
1	Front sport rim	\$ 2 550.00 X
1	Front brake disc	\$ 2 180.00 X
1	Front rim shaft	\$ Self 52.00 2
1	Side mirror - R/H	\$ 2 120.00
1	Handle-bar	\$ Self 135.00 2
1	Handle-bar balancer set	\$ 2 80.00
2	Brake levers	\$ 5/2 104.00 1 pc
1	Lower belly panel - R/H	\$ 2 250.00
1	Lower cowl centre grille	\$ 2 95.00
2	Footstep panels - R/H	\$ 2 310.00
1	Rear handle - R/H	\$ 2 85.00 X
1	Fairing cover (1 set)	\$ 2 1,150.00
1	Fork side cover - L/R/H	\$ 2 90.00
1	Front fender	\$ 2 85.00 X
1	Exhaust pipe assy	\$ 2 280.00
1	Exhaust cover	\$ 2 95.00
1	Exhaust cover center	\$ 2 65.00 X
		\$ 4,896.00
	Less 10%	\$ 489.60
		\$ 4,406.40

Special Net Items

2	Fork oils	\$ 1 30.00 X
2	Fork oil seals	\$ 1 56.00 X
1	Steering cone (1 set)	\$ 2 120.00
1	"X MAX" emblem	\$ 2 60.00
		\$ 266.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3634

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Lim Yong Tat

Accident Date : 12-Jun-20

Vehicle No : JTX716

Vehicle Model : Yamaha Xmax

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service	\$ 50.00 35
2	To ckeck wiring and reset headlamp focusing	\$ 80.00 X
3	To provide labour	\$ 380.00 280
4	To repair body frame	\$ 450.00 X
5	To re-spray painting	\$ 800.00 X
		\$ 1,760.00
Grand Total		\$ 6,432.40

Singapore Dollars: Six Thousand Four Hundred Thirty-Two and Cents: Forty only

3788.6
3026

EROFIA MOTOR TRADING PTE LTD