

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 23 June 2020

To : LKK

Attn: Bryan

Tel :

By Fax:

VEHICLE NO : FW 9364Z

Honda Wave 125

ACCIDENT DATE: 16/5/2020

Description	Qty	Quotation \$	
1 Handle Bar <i>ist</i>	1	135.00	✓
2 Balancer <i>n/s cut</i>	1 set	120.00	✓ 60.00
3 Brake Lever <i>n/n</i>	1	75.00	X
4 Front Centre Panel <i>cut</i>	1	90.00	✓
5 Head Lamp <i>wornly crack</i>	1	350.00	✓
6 Mirror <i>n/s broken</i>	1 set	150.00	✓ 75.00
7 Front LH Signal <i>crack</i>	1	95.00	✓
8 Front Mudguard <i>cut</i>	1	250.00	✓
9 Fork Tube <i>distort</i>	1	480.00	✓
10 Front RH side fairing <i>broken</i>	1	185.00	✓
11 Front RH Leg Shield <i>broken</i>	1	185.00	✓
12 Engine Lower Panel <i>broken</i>	1	135.00	✓
13 Exhaust Pipe <i>new</i>	1	650.00	X
14 Exhaust Guard <i>Dental</i>	1	250.00	✓
15 Brake Pedal <i>ist</i>	1	80.00	✓
16 Front Footrest <i>o/s ist</i>	1	95.00	✓
17 Foot Rest Rubber <i>o/s torn</i>	1	65.00	✓
18 Kick start/Shaft <i>ist</i>	1	135.00	✓
19 Engine Cover <i>broken</i>	1	190.00	✓
20 Rear Tail LH Panel <i>cut</i>	1	200.00	✓
21 Rear Pillion Foot Rest <i>ist n/s</i>	1	95.00	✓
22 Foot Rest Bracket <i>cut n/s</i>	1	125.00	✓

Belly Pan *Belly pan \$95 - crack ✓*

Sub-Total 4,135.00

Less 10% 413.50

Sub-Total 3,721.50

Main Stand *Main stand \$110 - ist ✓*

Gear Pedal *gear pedal \$105 - n/s ist ✓*

3585.00

10% 3226.50

VEHICLE NO : FW 9364Z

Honda Wave 125

Nett items

1 Towing fees <i>HM</i>	40.00 <i>X</i>
2 Labour to Remove & replace necessary parts, align & etc	250.00 <i>200/-</i>
3 Remove & replace Fork Tube, & oil seal	120.00 <i>80/-</i>
4 Supply body Decal Sticker <i>HM</i>	80.00 <i>50/-</i>
5 Rear Box <i>cut</i>	480.00 <i>180/-</i>
6 IU Unit <i>cut</i>	170.00 <i>150/-</i>

660.00

Sub-Total 1,140.00

Nett Total 4,861.50

5,140.50#

3886.50

R/S 2000/-

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

S9 TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*22/06/2025 @ 1730hrs
N/A Attached*

L/Sure 4 days

you (circled signature)

Repair limit.

LKK Auto

check MV

[Signature]