

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

15-Jun-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6149 E

1 pc	Front o/s head lamp	\$	1,028.00
1 pc	Bonnet grille	\$	385.00
1 pc	Front bumper	\$	531.00
1 pc	Front bumper emblem	\$	44.00
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	\$	32.00
1 pc	Front bumper o/s upper bracket	\$	16.00
1 pc	Front bumper o/s support bracket	\$	16.00
1 pc	Front bumper o/s protector	\$	51.00
1 pc	Washer tank	\$	47.00
1 pc	Washer tank motor	\$	48.00
1 pc	Front o/s fender	\$	384.00
1 pc	Front o/s fender inner shield	\$	120.00
1 pc	Front o/s wheel cover	\$	116.00
1 pc	Front o/s rim	\$	246.00
1 pc	Front o/s lower arm	\$	439.00
1 pc	Front o/s shock absorber	\$	330.00
1 pc	Front o/s ball joint	\$	59.00
1 pc	Front o/s knuckle arm	\$	547.00
1 pc	Front o/s knuckle bearing	\$	157.00
1 pc	Front o/s stabilizer link	\$	86.00
		\$	4,682.00
		Less 10%	\$ 468.20
			\$ 4,213.80

15-Jun-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6149 E

S/NETT

1 pc	Front bumper clips	\$	48.00
1 pc	Front o/s fender sticker	\$	30.00
1 set	Front o/s fender inner shield clips	\$	28.00

1 set	o/s door stickers	\$	100.00
	Sundry	\$	50.00
	To check front o/s wheel alignment	\$	80.00
	To dismantle / refit front o/s wheel undercarriage	\$	250.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s fender, etc.	\$	600.00
	To putty and spray painting on front bumper, front o/s fender, front o/s door,	\$	600.00
	To apply rustproofing on the repaired and replaced panels.	\$	150.00
		\$	<u>6,329.80</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.