

Section A - Accident Details

Registration Number	SHB739Y
Case Reference Number	TAX/06/20/2026
Registration Date	10/11/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	WONG LEE SENG
Type of Accident	Head to Rear
Accident Date and Time	18/6/2020 8:10 AM
Accident Reported Date and Time	18/6/2020 11:18 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24107261
Special Instruction to ARC, if any	TO / REAR PORTION
Prepared Date and Time	19/6/2020 8:01 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,314.00	\$700.00
Total Spray Cost	\$2,394.00	\$900.00
Total Spare Part Cost	\$7,266.44	\$1,270.74
Total Other Cost	\$1,385.00	\$110.00
TOTAL COST	\$12,359.44	\$2,980.70
Lump Sum Total	\$12,350.00	\$3,000.00 (L/S)
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	23/06/2020 8:57 AM	22/06/2020 4:52 PM
Signature		
Remarks	Total number of repair days = 5 days. SUP = +2 days.	L/S, after paint

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2007-0089	Invoice Number	
Quotation Date	09.07.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$500.00
TO REPAIR REAR END PANEL	\$300.00	\$200.00
Total Labour	\$1,314.00	\$700.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY REAR SPOILER	\$180.00	\$100.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$2,394.00	\$900.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$30.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,385.00	\$110.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check X
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	100.00	\$0.00	Replace	Old Damage X
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given X
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given X
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace ✓
		58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given X
		58327-47020	EXHAUST HEAT SHIELD, REAR	0.00	\$107.40	0.00	\$0.00	Replace	Check X
		17430-37380	EXHAUST TAIL PIPE	0.00	\$656.20	0.00	\$0.00	Replace	Not Given X
		17565-22030	SUPPORT, EXHAUST REAR	0.00	\$33.60	0.00	\$0.00	Replace	Not Given X
		67005-47241	TAILGATE ASY	1.00	\$1,007.90	100.00	\$0.00	Replace	Repair ✓
		69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Not Given X
		69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Not Given X
		67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Not Given X
		69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Not Given X
		76801-47070-B0	TAILGATE OUTSIDE GARNISH	1.00	\$504.90	100.00	\$0.00	Replace	Repair ✓
		75310-47020	EMBLEM REAR	1.00	\$60.30	25.00	\$45.23	Replace	Replace ✓
		75442-47030	NAME PLATE (PRIUS)	1.00	\$60.80	25.00	\$45.60	Replace	Replace ✓
		75443-47030	NAME PLATE (TOYOTA)	1.00	\$51.90	25.00	\$38.93	Replace	Replace ✓
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace ✓
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace ✓
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace ✓
		76085-47910	SPOILER REAR	1.00	\$953.70	100.00	\$0.00	Replace	Repair ✓
		58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check X
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X
		58490-47140B0	BOARD ASSY, RR RH	0.00	\$379.20	0.00	\$0.00	Replace	Not Given X
		58427-47040	SPACER, RR FLOOR	0.00	\$130.60	0.00	\$0.00	Replace	Not Given X
		64730-47031B2	PANEL ASSY, DECK RH	0.00	\$307.00	0.00	\$0.00	Replace	Not Given X
			BATTERY	0.00	\$278.00	0.00	\$0.00	Replace	Check X
		74481-47050	BATTERY CLAMP	0.00	\$16.10	0.00	\$0.00	Replace	Not Given X
		74440-47030	BATTERY TRAY	0.00	\$42.80	0.00	\$0.00	Replace	Check X
		52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given X
		81551-47180	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace ✓
		61621-47030	TROUGH, BACK DOOR	0.00	\$110.90	0.00	\$0.00	Replace	Not Given X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/07/2020
User ID : PohSuan

	61604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	✓
		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
	65637-47021	FENDER LINER RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given	X
	62940-16060	DUCT ASSY, QUARTER	0.00	\$70.40	0.00	\$0.00	Replace	Not Given	X
	62710-47130	QUARTER GLASS RR/RH	0.00	\$846.50	0.00	\$0.00	Replace	Not Given	X
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	58302-47030	FLOOR PANEL RR/RH	0.00	\$209.90	0.00	\$0.00	Replace	Check	X
Total				\$11,275.51		\$1,276.64			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		62940-16060	DUCT ASSY, QUARTER	1.00	\$70.40	25.00	\$52.80	Replace	Replace
Total					415.70		\$311.78		

BT
BT
CRU

1588.42 /

- 20% /

1270.74 /

+ 700.00 /

+ 1010.00 /

2980.74 /

L/S \$3000/- /
5 days