

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Adress : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : MSIG Insurance (Singapore) Pte Ltd
Motor Claims Dept

Date : 26 Jun 2020

Dear Sirs :

Fax : 6224 1047

RE : ESTIMATE COST FOR MADZA 3 5DOOR - SJL6009E ACCIDENT INVOLVING SJL6009E & FBG64E ON 19/06/2020

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bumper	1pc	\$ 1,118.40
2	Rear bumper retainer @\$37.40ea	2pcs	\$ 74.80
3	Rear sensor rh	1pc	\$ 203.60
4	Rear bumper lower garnish	1pc	\$ 58.80
5	Rear lamp rh (outer)	1pc	\$ 971.40
6	Rear bootlid lamp o/s.	1pc	\$ 465.90
7	Madza3	1pc	\$ 78.20
8	Skyactiv	1pc	\$ 66.80
9	Emblem	1pc	\$ 66.80
			<hr/>
			\$ 3,104.70
			\$ (620.94)
			<hr/>
	Sum Carried Forward		\$ 2,483.76

Less 20%

Sum Carried Forward \$ **2,483.76**

Labour Charge & Misc

To remove, repair, replace & install } \$ 600.00
damaged parts. }

To R & R light wiring \$ 60.00

To R & R sensor wiring \$ 80.00

To putty & spray painting \$ 600.00

Total **\$ 3,823.76**

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.