

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 13 Jul 2020

Preliminary Advice

Insured Vehicle No	: FBG64E	Accident Date	: 19/06/2020
TP Vehicle No	: SJL6009E	Assignment Date	: 22/06/2020
Make	: MAZDA 3	Est. Duration of Repair	: 3
Date of Inspection	: 26/6/2020		
Inspection At	: WOON MENG MOTOR PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,823.76
Revised Amount	:S\$	2,000.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,000.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair-The above survey was conducted on a 'Without Prejudice' basis
 () The above survey was conducted on a 'without prejudice' basis.