

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungai Kadut Ave, Singapore 729666 Tel : 63268523

(Email Adress : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : MSIG Insurance (Singapore) Pte Ltd
Motor Claims Dept

Date : 26 Jun 2020

Dear Sirs :

Fax : 6224 1047

RE : ESTIMATE COST FOR MADZA 3 5DOOR - SJL6009E
ACCIDENT INVOLVING SJL6009E & FBG64E ON 19/06/2020

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bumper <i>de✓</i>	1pc	1118.40 <i>de✓</i>
2	Rear bumper retainer @\$RH?	2pcs	74.80 <i>Xun.</i>
3	Rear sensor rh <i>dis✓</i>	1pc	203.60 <i>dis✓</i>
4	Rear bumper lower garnish <i>A-</i>	1pc	58.80 <i>ut✓</i>
5	Rear lamp rh (outer) ?	1pc	971.40 <i>Xun</i>
6	Rear bootlid lamp o/s. <i>Cna✓</i>	1pc	465.90 <i>Cna✓</i>
7	Madza3 <i>nei✓</i>	1pc	78.20 <i>nei✓</i>
8	Skyactiv <i>nei✓</i>	1pc	66.80 <i>nei✓</i>
9	Emblem <i>nei✓</i>	1pc	66.80 <i>nei✓</i>
			<u>\$ 3104.70</u>
			<u>(620.94)</u>
			\$ 2483.76

Sum Carried Forward

Less 20%

2058.50

1646.80.

Sum Carried Forward

Labour Charge & Misc

To remove, repair, replace & install damaged parts. * photo rear end panel	400	}	\$600
To R & R light wiring.	30	}	\$60
To R & R sensor wiring	30	}	\$80
To putty & spray painting.	400	}	\$600

Total

\$1340 -
3823.76

Taufik 97495749 860
- WP -
26/6/20 @ 245
3 days
Resurvey before/after repair

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

1646.80
860
2506.80
1/5/2000
03 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: