

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD3334B

DATE: 19. Jun. 2020

MAKE : HYUNDAI

MODEL : i40

DOA: 19. Jun. 2020

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	Rear Bumper			\$1,106.00	de
10	Rear Bumper Clips		\$2.20	\$22.00	net
1	Rear Bumper Sponge			\$103.50	?
1	Rear Bumper Reinforcement			\$428.40	?
1	Rear Bumper Undercover			\$228.00	x
1	Rear Bumper Reflector - RH			\$32.00	?
SUB TOTAL				\$1,919.90	
LESS 20%				\$383.98	
DISCOUNTED TOTAL				\$1,535.92	
1	Rear Bumper Rubber Mat			\$50.00	Nett
Labour Charge				\$50.00	
1	Panel Beating			\$300.00	280
1	Spray Painting Charge			\$250.00	200
1	Wiring Charge			\$50.00	30
TOTAL LABOUR				\$600.00	
ESTIMATE TOTAL				\$2,185.92	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal method must be followed
- Supplier of parts must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Larry Ng

Tanfer 97495744
WP 22/6/20 @ 305pm
Lumpsum
Resurvey after repair 02 days
Tanfer @ lkkauto.com

