

View Received Message

This mail is associated with :

***SLX7547A (6121323200SG)**

OD

Jun 20 2020 12:00PM

[TEO SHER LING (ZHANG SILING)]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)


From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 24/08/2020 15:13 PM.
LKK_HQ

Subject Alert - Adj Mandate Approved (S\$11962.16) - SLX7547A - Claim Handler: Chan, Yoke Shi

Approved:11962.16.

DOCUMENTS SUMMARY

There are no documents.



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 38451

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0439/2020/NS
Date	:	22-Jun-20

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Teo Sher Ling
Address	:	Blk 325 Hougang Avenue 7 #05-319 Singapore 530325
Telephone	:	HP +65 96842855
Type of Claim	:	Own Damage Claim
Policy No.	:	1800035757
Vehicle No	:	SLX 7547 A
Model Code	:	Audi A3 sportsback 1.0 TFSI
Model / Year	:	Apr-18
Engine No	:	CHZ 646361
Chassis No	:	WAUZZZ8V8JA074342
Mileage	:	30604
Date In	:	21-Jun-20
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	20-Jun-20
Place of Accident	:	Pemimpin Drive

Premium Automobiles

55 Ubi Road 1, Singapore 408700
Tel: 6366 2323 Fax: 6801 1144

Telefax

Estimated Labour Charges for Accident Vehicle. SLX 7547 A

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$ 280.00	/
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	X
3	To dismantle rhs front door panel trim. To renew rhs wing mirror assy.	S/N \$ 350.00	/ \$350-00
4	To remove front bumper, rhs front fender and rhs headlight. To renew rhs front fender. To repair rhs front door. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00	1000 \$1000
5	To respray front bumper, rhs front fender, bonnet, rhs wing mirror cover, rhs upper A-pillar and rhs front door.	\$ 4,500.00	1250 / 800 \$1800
6	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00	/ \$280-00
7	To carry out diagnostic check.	S/N \$ 192.00	/ \$192-00
SUB TOTAL LABOUR CHARGES		: \$ 8,762.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7547 A

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT FENDER - RH <i>bt</i> ✓	\$ 802.00	<i>\$641-60</i>
2	FRONT FENDER ATTACHMENT PARTS <i>ne</i> ✓	\$ 68.00	<i>\$54-40</i>
3	FRONT FENDER BRACKET - RH <i>bt</i> ✓	\$ 45.00	<i>\$36-00</i>
4	FRONT FENDER CLOSING ELEMENT - RH ?	\$ 58.00	
5	FRONT FENDER BRACE - RH ?	\$ 90.00	
6	FRONT FENDER BRACKET - RH ?	\$ 26.00	
7	WHEEL HOUSING LINER - RH ?	\$ 159.00	
8	WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$ 54.00	
9	LED HEADLIGHT - RH ?	\$ 5,193.00	
10	EXTERIOR MIRROR MOUNTING - RH <i>crn</i> ✓	\$ 964.00	<i>\$771-20</i>
11	MIRROR CAP - RH <i>mis</i> ✓	\$ 141.00	<i>\$112-80</i>
12	MIRROR GLASS - RH <i>bro</i> ✓	\$ 1,563.00	<i>\$1250-40</i>
13	FRONT DOOR WINDOW - RH <i>scr</i> ✓	\$ 217.00	<i>\$173-60</i>
14	FRONT WINDOW SLOT SEAL - RH <i>scr</i> ✓	\$ 254.00	<i>\$203-20</i>
15	ROOF MOULDING - RH <i>scr</i> ✓	\$ 556.00	<i>\$444-80</i>
16	WATER DEFLECTOR STRIP - RH X	\$ 63.00	
17	WINDOW GUIDE - RH <i>scr</i> ✓	\$ 396.00	<i>\$316-80</i>
18	CORNER TRIM - RH X	\$ 43.00	
19	B PILLAR TRIM - RH X	\$ 98.00	
20	FRONT ALUMINIUM RIM - RH <i>scr</i> ✓	\$ 666.00	<i>\$532-80</i>
21	SUNDRIES ?	\$ 300.00	<i>\$180-96</i>

TOTAL SPARE PARTS CHARGES

: \$11,756.00

TOTAL LABOUR CHARGES

: \$ 8,762.00

GRAND TOTAL

: \$20,518.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Rasul - Hp 90010068
Surveyed Date : 22/06/2020 @ 1610
Authorised Date :
Excess Cost : 5 days
Liability :
Remarks : ~~2nd~~ EXCESS: TBA

REPAIR
Resurvey before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0439/2020/NS

Date

25-Jun-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SLX 7547 A

Model No

Audi A3 sportback 1.0 T

Quantity	Description	Unit Price	Amount
Parts			
1	Lower arm rhs front ? bt /	\$ 359.00	\$287.20
2	Guide joint rhs front ? bt /	\$ 119.00	\$95.20
3	Wheel bearing housing rhs front ? bt /	\$ 555.00	\$444.00
4	Wheel bearing assy rhs front ? rec /	\$ 479.00	\$383.20
5	Shock absorber rhs front ? bt /	\$ 256.00	\$204.80
6	Tie rod rhs ? bt /	\$ 88.00	\$70.40
7	Tie rod end rhs ? bt /	\$ 121.00	\$96.80
Labours			
1	To remove and renew rhs front wheel suspension assy.	s/n \$ 1,800.00 /	\$1800.00
2	To carry out pre-wheel alignment.	s/n \$ 240.00 /	\$240.00

TOTAL

\$ 4,017.00

For Premium Automobiles Pte Ltd

Authorised Signature

P. Tan
25/06/2020

*Subject to
insurer approval
2 days extra*

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 38451

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0439/2020/NS
Date : 22-Jun-20

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Rasul

*8 days exclude 1 Sunday - added
jobs - jb 13 Aug 20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Teo Sher Ling
Address : Blk 325 Hougang Avenue 7
#05-319
Singapore 530325
Telephone : HP +65 96842855
Type of Claim : Own Damage Claim
Policy No. : 1800035757
Vehicle No : **SLX 7547 A**
Model Code : Audi A3 sportsback 1.0 TFSI
Model / Year : Apr-18
Engine No : CHZ 646361
Chassis No : WAUZZZ8V8JA074342
Mileage : 30604
Date In : 21-Jun-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Jun-20
Place of Accident : Pemimpin Drive

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLX 7547 A

S/N	Nature of Jobs		Estimated Charges	Surveyor's recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$	280.00	nc
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	nc
3	To dismantle rhs front door panel trim. To renew rhs wing mirror assy.	S/N \$	350.00	\$ 350.00
4	To remove front bumper, rhs front fender and rhs headlight. To renew rhs front fender. To repair rhs front door. Re-organise crash management components. Reinstall all parts removed.	\$	2,800.00	\$ 1,000.00
5	To respray front bumper, rhs front fender, bonnet, rhs wing mirror cover, rhs upper A-pillar and rhs front door.	\$	4,500.00	\$ 1,800.00
6	To renew rhs front rim and carry out wheel alignment.	S/N \$	280.00	\$ 280.00
7	Added labour charges - see attached	\$	2,040.00	\$ 2,040.00
8	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
SUB TOTAL LABOUR CHARGES		:	\$ 10,802.00	\$ 5,662.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7547 A

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT FENDER - RH	\$ 802.00	\$ 641.60
2	FRONT FENDER ATTACHMENT PARTS	\$ 68.00	\$ 54.40
3	FRONT FENDER BRACKET - RH	\$ 45.00	\$ 36.00
4	FRONT FENDER CLOSING ELEMENT - RH	\$ 58.00	
5	FRONT FENDER BRACE - RH	\$ 90.00	
6	FRONT FENDER BRACKET - RH	\$ 26.00	
7	WHEEL HOUSING LINER - RH	\$ 159.00	
8	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 54.00	
9	LED HEADLIGHT - RH	\$ 5,193.00	
10	EXTERIOR MIRROR MOUNTING - RH	\$ 964.00	\$ 771.20
11	MIRROR CAP - RH	\$ 141.00	\$ 112.80
12	MIRROR GLASS - RH	\$ 1,563.00	\$ 1,250.40
13	FRONT DOOR WINDOW - RH	\$ 217.00	\$ 173.60
14	FRONT WINDOW SLOT SEAL - RH	\$ 254.00	\$ 203.20
15	ROOF MOULDING - RH	\$ 556.00	\$ 444.80
16	WATER DEFLECTOR STRIP - RH	\$ 63.00	
17	WINDOW GUIDE - RH	\$ 396.00	\$ 316.80
18	CORNER TRIM - RH	\$ 43.00	
19	B PILLAR TRIM - RH	\$ 98.00	
20	FRONT ALUMINIUM RIM - RH	\$ 666.00	\$ 532.80
21	Added parts - see attached	\$ 1,977.00	\$ 1,581.60
22	SUNDRIES	\$ 300.00	\$ 180.96

TOTAL SPARE PARTS CHARGES

: \$ 13,733.00 \$ 6,300.16

TOTAL LABOUR CHARGES

: \$ 10,802.00 \$ 5,662.00

GRAND TOTAL

: \$ 24,535.00 \$ 11,962.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0439/2020/NS 25-Jun-20 Glory Tan 1 of 1 SLX 7547 A Audi A3 sportsback 1.0 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	Lower arm rhs front	\$ 359.00	\$ 287.20
2	Guide joint rhs front	\$ 119.00	\$ 95.20
3	Wheel bearing housing rhs front	\$ 555.00	\$ 444.00
4	Wheel bearing assy rhs front	\$ 479.00	\$ 383.20
5	Shock absorber rhs front	\$ 256.00	\$ 204.80
6	Tie rod rhs	\$ 88.00	\$ 70.40
7	Tie rod end rhs	\$ 121.00	\$ 96.80
			\$ 1,581.60
Labours			
1	To remove and renew rhs front wheel suspension assy.	s/n \$ 1,800.00	\$ 1,800.00
2	To carry out pre-wheel alignment.	s/n \$ 240.00	\$ 240.00
	Labour		\$ 2,040.00
	Materials		\$ 1,581.60
	Total		\$ 3,621.60
	TOTAL	\$ 4,017.00	

For Premium Automobiles Pte Ltd

 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant