

Fong Motors

1, Kaki Bukit Ave 6, #01-45/27, Autobay, Singapore 417883

Vehicle No. SMP1904Y
Make/Model TOYOTA ISIS
Year :
Chassis No. ZNM10-0056387

TP AIG

DATE :

Asks: ZNM100056387

ESTIMATE FOR SMP1904Y

PARTS LIST

			Unit Price		
1	1 pc	Rear Boot Lid Lock <i>cracked</i>	\$ 490.60	\$ 490.60	<i>385</i>
2	1 pc	Rear Boot Lid <i>cracked</i>	\$ 1,267.40	\$ 1,267.40	<i>✓</i>
3	1 pc	Emblem - Logo <i>Nec</i>	\$ 105.10	\$ 105.10	<i>68</i>
4	1 pc	Boot lid outer handle - Chrome <i>cracked</i>	\$ 254.70	\$ 254.70	<i>✓</i>
5	1 pc	Boot lid inner handle - Black <i>Nec</i>	\$ 43.80	\$ 43.80	<i>X</i>
6	1 pc	Rear boot lid inner cover <i>cracked</i>	\$ 482.80	\$ 482.80	<i>✓</i>
7	1 pc	Rear boot lid weather strip <i>cracked</i>	\$ 303.80	\$ 303.80	<i>✓</i>
8	1 pc	Rear end panel <i>Deformed</i>	\$ 439.60	\$ 439.60	<i>✓</i>
9	1 pc	Rear end panel garnish <i>Deformed</i>	\$ 303.80	\$ 303.80	<i>✓</i>
10	1 pc	Rear bumper <i>Deformed</i>	\$ 1,060.20	\$ 1,060.20	<i>855</i>
11	2 pc	Rear bumper lamp <i>RH cracked</i>	\$ 253.10	\$ 506.20	<i>253.10</i>
12	2 pc	Rear bumper bracker <i>Nec</i>	\$ 68.40	\$ 136.80	<i>X</i>
13	2 pc	Rear no. plate lamp <i>Nec</i>	\$ 52.60	\$ 105.20	<i>X</i>
14	2 pc	Bumper side retainer <i>Nec</i>	\$ 58.60	\$ 117.20	<i>✓</i>
				\$ 5,411.40	

1	Rear reverse camera <i>Nec</i>	S/N	\$ 480.00	<i>X</i>
2	Reverse sensor <i>Damaged</i>	S/N	\$ 350.00	<i>200</i>
3	End panel garnish clip <i>Nec</i>	S/N	\$ 40.00	<i>10</i>
4	Rear Bumper clip <i>Nec</i>	S/N	\$ 40.00	<i>30</i>
5	Rear windscreen glass moulding <i>Nec</i>	S/N	\$ 108.50	<i>✓</i>
			\$ 1,018.50	
Total parts:			\$ 6,429.90	

Labour:

1	Remove and refit windscreen glass	\$ 150.00	<i>120</i>
2	To spray rear LH/RH fender, rear bumper, boot lid, and end panel	\$ 1,200.00	<i>800</i>
3	To knock and change parts	\$ 1,000.00	<i>800</i>
4	To remove and replace reverse sensor/ camera	\$ 180.00	<i>80</i>
		\$ 80.00	<i>30</i>
		\$ 100.00	<i>60</i>

Total labour: \$ 2,710.00

Total Estimated: \$ 9,139.90

5 LKK Auto Consultants hence notify the Repairer of the following:
6 To resurvey the repairer spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4610

Total: 5786.30

1/s: 4.610

06 Days.