

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Abdul Basith Bin Ramli

Accident Date : 10-Mar-20

Vehicle No : FBM138U

Vehicle Model : BMW
S1000RR ABS

Estimated Repair Costs

Qty	Description	Not Authorized	Amount S(\$)
	<u>List Items</u>		
1	Front fork keg - R/H	11 \$	2,077.00 X
1	Front fork keg - L/H	11 \$	2,077.00 X
1	Lower fork cross brace	sent \$	1,930.00 ✓
1	Fork bridge cover	sent \$	62.00 ✓
2	Bearing	11 \$	442.00 X
1	Coverig plate	bro \$	27.00 ✓
1	Upper fork cross brace	one \$	1,575.00 ✓
2	Fork tube with slider sleeves, gold	20/sent \$	6,126.00 ✓
2	Fork oil seal & dust cover set	nn \$	592.00 X
1	Front rim black	n \$	3,857.00 X
1	Front rim shaft	11 \$	525.00 X
2	Front rim bearing	11 \$	100.00 X
2	Front rim dust cover	11 \$	60.00 X
1	Front brake disc	sent \$	1,562.00 ✓
1	Widshield	one \$	466.00 ✓
1	Front wheel cover	10.5 \$	512.00 ✓
1	Steering damper	Damaged \$	1,789.00 ✓
1	Handle-bar - R/H	sent \$	871.00 ✓
1	Front panel carrier	\$	758.00 ?
2	Mirrors - R/L H	n/s m/s o/s car \$	830.00 ✓
1	Head lamp - R/H	bro \$	1,391.00 ✓
1	Head Lamp - L/H	bro \$	1,445.00 ✓
1	Head lamp cover	bro \$	45.00 ✓
2	Bulb H7/55W	11 \$	84.00 X
2	Rear signals - R/L H	o/s one \$	326.00 1pc
2	ISA screw	11 \$	16.00 X
2	Hex nut	11 \$	8.00 X
1	Air duct	one \$	796.00 ✓
1	Radiator	put \$	2,759.00 ✓
1	Expansion tank	thin \$	172.00 ✓
1	Oil cooler	two/put \$	2,166.00 ✓
1	Handle-bar weight	scr \$	139.00 ✓
1	Brake lever	scr \$	458.00 ✓

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Abdul Basith Bin Ramli

Accident Date : 10-Mar-20

Vehicle No : FBM138U

Vehicle Model : BMW
S1000RR ABS

Estimated Repair Costs

1	Fan		\$	1,248.00 ?
2	Front top fairing - R/L H	320	\$	1,332.00 ✓
2	Front side trim panel - R/L H		\$	650.00 ?
2	Front side fairing - R/L H	320	\$	1,912.00 ✓
2	Front side lower cover - R/L H	320	\$	1,962.00 ✓
1	Tank front cover	one	\$	451.00 ✓
1	Front centre air intake		\$	796.00 ?
2	Front signals - R/L H	one	\$	478.00 ✓
1	Front footrest - R/H	one	\$	1,682.00 X
1	Expanding rivet	one	\$	7.50 ✓
4	Plug in retainer	11	\$	13.20 X
4	Self locking plug nut	11	\$	40.00 X
2	pin	11	\$	18.00 X
2	Heat shield - R/L H	1	\$	74.00 X
1	Exhaust pipe assy	1/2 set	\$	5,520.00 ✓
1	Exhaust manifold with front muffler		\$	8,400.00 ?
1	Switching valve		\$	640.00 ?
1	Fuel tank	1	\$	5,977.00 X
1	Throttle cover	one	\$	1,102.00 ✓
1	Headlamp trim		\$	884.00 ?
1	Control unit with EWS Data	11	\$	6,200.00 X
1	Wiring harness set	1	\$	2,038.00 X
1	Front panel carrier		\$	380.00 ?
1	Footrest - R/H	11	\$	318.00 X
1	Stopper	11	\$	31.00 X
1	Brake pedal	11	\$	650.00 X
1	Throttle grip		\$	967.00 ?
1	Air inlet duct		\$	405.00 ?
			\$	80,218.70
Less 10%			\$	8,021.87
			\$	72,196.83

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Abdul Basith Bin Ramli

Accident Date : 10-Mar-20


Vehicle No : FBM138U

Vehicle Model : BMW
S1000RR ABS

Estimated Repair Costs

<u>Special Nett Items</u>			
1	Number Plate (1 set)	<i>net</i> \$	28.00 <i>10</i>
1	Badge	\$	203.00 <i>?</i>
		\$	231.00
<u>S/No.</u>	<u>Labour</u>		
1	To provide towing	\$	50.00 <i>35</i>
2	To check wiring and reset headlamp focusing	\$ <i>11</i>	80.00 <i>x</i>
3	To set control unit	\$	800.00 <i>?</i>
4	To respray painting	\$	680.00 <i>450</i>
5	To provide labour	\$	500.00 <i>400</i>
		\$	2,110.00
Grand Total		\$	74,537.83

Dollars: Eighty-Eight Thousand Thirty-Seven and Cents: Eighty-Three only


EROFIA MOTOR TRADING PTE LTD