

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 511B*Not Authored*

AAD2006-051

*Presumy B4poin**@ 50%*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

22 JUN 2020**SHD 511B**

VF1ABL15AUC283480

RENAULT

LATITUDE

19.6.2020

TOKIO MARINE

10/07/2017

PART		LIST	
1	BUMPER COVER FRT	\$	R 747.20
1	BUMPER SPOILER FRT	\$	L 344.70
1	BUMPER ABSORBER FRT	\$	L 394.68
1	BUMPER RETAINER FRT LH	\$	L 101.40
1	BUMPER BRACKET FRT LH	\$	R 184.60
1	BUMPER UNDERTRAY FRT	\$	L 292.50
1	BUMPER GRILLE LOWER FRT	\$	L 147.00
1	BUMPER FOG LAMP GRILLE LH	\$	L 207.21
1	RADIATOR GRILLE	\$	L 969.90
1	RADIATOR GRILLE FRAME	\$	L 686.00
1	HEADLAMP LH	\$	L 743.60
1	BONNET	\$	R 1,312.70
1	FENDER PANEL FRT LH	\$	R 414.40
1	WHEELARCH FRT LH	\$	L 112.30
1	FENDER BRACKET LOWER LH	\$	L 11.80
1	AIR CLEANER BOX	\$	L 464.20
1	AIR CLEANER HOSE	\$	L 175.85
1	AIR CLEANER LOWER	\$	L 271.26

TOTAL	\$	7,581.30
10%	\$	758.13
	\$	6,823.17

Trans-cab Auto Services Pte Ltd

AAD2006-051

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 511B

Special Nett

1SET RADIATOR GRILLE FRAME CLIP	\$	nn	55.00	}	X
1SET BUMPER CLIP FRT	\$	nn	69.00		
1SET BUMPER BRACKET CLIP FRT LH	\$	nn	30.00		
1SET BUMPER RETAINER CLIP FRT LH	\$	nn	35.00		
1 RADIATOR GRILLE SCREW	\$	nn	25.00		
1SET BUMPER GRILLE LOWER CLIP	\$	nn	69.00		
1 FRONT RENAULT TYRE 215/60/16	\$	nn	300.00		
1 FRONT RENAULT TYRE RIM	\$	nn	380.00		
1 FRONT RENAULT TYRE RIM COVER	\$	nn	50.00		
1 Front licence plate with holder	\$	nn	100.00		
1SET WHEELARCH CLIP FRT LH	\$	nn	38.00		
TOTAL	\$		1,151.00		

TOTAL PARTS \$ 7,974.17**Labour**

To rust-proofing of the affected areas.	\$	nn	170.00	X
To remove and refit interior fittings, trimings, garnish, and others, to enable repair.	\$	nn	380.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		6,000.00	609
To Transfer Of Front Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn	170.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X

To Check Electrical Lighting Concerned.

\$ 170.00

Trans-cab Auto Services Pte Ltd

AAD2006-051

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 511B

Putty and spray painting of the affected portion. \$ 6,000.00

TOTAL \$ 13,230.00

4401

Over All Total \$ 21,204.17

(PART BY PART) Repair Days

20 DAYS

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: