

## KGC WORKSHOP PTE LT

Satisfaction Secure .

Renny Atra Pains

Soong Weng Chung, Jeffrey 14 Ang Mo Kio St 63

Registraion No: SLA 8423M

Block B

Singapore 569116

TP 200602 22/6/2020 Date

No of Page

: 1/2

Model:

Hyundai Elantra 1.6

Sub-Total for Parts: \$

KHMD841CMHU099406

1,249.60

Accident Date: Our Ref:		19-Jun-20 TP 200602	Chassis No:	KHMD841CMH0099400	
			Engine Capacity	: 1591	<u>'1</u>
		Items	Unit Price		mount
1 2 3 4	Qty 1 2 1 2	Rear bumper Rear bumper retainer Rear bumper reinforcement Rear tail light reflector	\$ 680.00 \$ 44.30 \$ 320.80 \$ 48.80	\$	320.80 7 Re 97.60 x
			-20% Total for spare parts		1,187.00 237.40 949.60
Speci 1 2 3	l set l set l set	Rear Bumper Clips No.Plate with Casing reverse sensor	\$ 50.00 \$ 50.00 \$ 200.00	\$ \$ \$	Ne. 50.00 × Se. 50.00 × 200.00 7
			Total for SP	\$	300.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



S/No	Qty	Items	Unit Price	Amount
0/110	~ ~			2001
1		ntle, replace, cut, weld, knock or repair parts, inclusive of replace	out dents to straighten accident parts asment parts.	500.00
2	To putty affected a	and spray paint on all accident d	lamage parts and other accident	2201 500.00
3	To check	wiring system to facilitate repai	r and refit the same	80.00 101
4	Apply rus	st proofing on the adjacent panel	ls	nn 80.00 X
5	Remove a	nd install reverse sensor	10 1. See	80.00 501
	1101110		TOTAL AMOUNT:	1,160.00
			OVERALL COST :	2,409.60