

INSURANCE CO. : **INDIA**


Supplementary Parts For Registration No.: **SDX 9128 H**

| <b><u>Materials</u></b> |                                           | <b><u>Cost (\$)</u></b> |
|-------------------------|-------------------------------------------|-------------------------|
| 1                       | Dam, tailgate side <b>NEC</b> ✓           | 27.00                   |
| 2                       | Buzzer, keyless operatio, RR <b>CRA</b> ✓ | 91.00                   |
| Total Materials         |                                           | 118.00                  |

| <b><u>Labour</u></b> |                                                                  | <b><u>Cost (\$)</u></b> |
|----------------------|------------------------------------------------------------------|-------------------------|
| 1                    | Conduct diagnostic check using MUT tester and clear trouble code | 200.00 ✓                |
| 2                    | Check wiring and chassis electrical system                       | 30.00 ✓                 |
| Total Labour         |                                                                  | 230.00                  |
| Taxable Amount       |                                                                  | 348.00                  |
| 7% GST               |                                                                  | 24.36                   |
| <b>Grand total</b>   |                                                                  | <b><u>372.36</u></b>    |

Thank You.

Yours faithfully  
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD



LOI AITONG  
SENIOR OFFICER - ADMIN  
TEL: 6568 4556 / 6568 4501  
FAX : 6567 5258 / 6565 1240