



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

| Invoice Name & Address | Owner Name & Vehicle Info |
|-----------------------------|---|
| GWEE CHOW | Cust No/Name KCV10703/GWEE CHOW |
| BLK 430 CLEMENTI AVE 3 | Reg No/Reg Date SDX9128H / 15/03/201 |
| #07-386 | Date In/Mileage / 0 |
| SINGAPORE 120430 | Chassis No GF7W0600474 |
| Contact No Mobile: 96908690 | Engine No 4J11AC0380 |
| | Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) |
| | Colour/Trim W01 WHITE PEARL / BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | |
|--|-------|-------------------|-----|---------------|------------|-------|---------|
| CSM00041 | Cash | 22/06/2020/ 15:22 | QUD | 247 / DonBong | 54081 | | |
| Description of Goods / Services | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 | | | | | | | 2750.00 |
| RENEW ACCIDENT DAMAGED PARTS ON REAR TAILGATE, REAR BUMPER FACE, | | | | | | | 1100 |
| REPAIR RH REAR FENDER, REPAIR REAR END PANEL | | | | | | | 240.00 |
| E PNT88000 | | | | | | | 80.00 |
| REMOVE AND TRANSFER REAR WINDSCREEN GLASS | | | | | | | 80 |
| M SUNDRY | | | | | | | 100.00 |
| SUPPLY REAR WINDSCREEN SEALANT | | | | | | | 80 |
| E PNT88000 | | | | | | | 160.00 |
| REMOVE AND INSTALL PARKING ASSIST | | | | | | | 840 |
| M SUNDRY | | | | | | | 2100.00 |
| APPLY BODY SEALANT | | | | | | | 60 |
| E PNT98000 | | | | | | | 80.00 |
| PAINT WORK SPRAY REAR END PANEL, REAR TAILGATE, REAR BUMPER, | | | | | | | ? |
| RH REAR FENDER AND AFFECTED PORTION | | | | | | | 220.00 |
| M SUNDRY | | | | | | | 50.00 |
| PERFORM RUST PREEVENTION | | | | | | | ? |
| M SUNDRY | | | | | | | 380.00 |
| SUPPLY REAR PARKING SENSOR | | | | | | | ? |
| M SUNDRY | | | | | | | 550.00 |
| SUPPLY C&C LOGO | | | | | | | 20 |
| M SUNDRY | | | | | | | 50.00 |
| RE-APPLY ZERTONA BODY COATING ON AFFECTED AREA (invoiced) | | | | | | | |
| E PNT88000 | | | | | | | |
| TO REMOVE AND REPLACE ELECTRIC AUTO TAILGATE | | | | | | | |
| M SUNDRY | | | | | | | |
| SUNDRIES | | | | | | | |
| M LATCH, TAILGATE ?? | | | | 1.00 | 383.00 | 00.00 | 383.00 |
| M STRIKER, TAILGATE LATCH ? | | | | 1.00 | 20.00 | 00.00 | 20.00 |
| M W/STRIP, TAILGATE OPENING ? | | | | 1.00 | 213.00 | 00.00 | 213.00 |
| M PANEL ASSY, TAILGATE 4 | | | | 1.00 | 984.00 | 00.00 | 984.00 |
| M GARNISH, TAILGATE X | | | | 1.00 | 494.00 | 00.00 | 494.00 |
| M DAM, TAILGATE, UPR per | | | | 1.00 | 13.00 | 00.00 | 13.00 |
| M DAM, TAILGATE, UPR per | | | | 2.00 | 13.00 | 00.00 | 26.00 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|---|
| GWEE CHOW BLK 430 CLEMENTI AVE 3 #07-386 SINGAPORE 120430 Contact No Mobile: 96908690 | Cust No/Name KCV10703/GWEE CHOW Reg No/Reg Date SDX9128H / 15/03/201 Date In/Mileage / 0 Chassis No GF7W0600474 Engine No 4J11AC0380 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim W01 WHITE PEARL / BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---------------------------------|------------------------------|-------------------|-----|---------------|------------|--------|--------|--------|
| CSM00041 | Cash | 22/06/2020/ 15:22 | QUD | 247 / DonBong | 54081 | | | |
| Description of Goods / Services | | | | Qty | Unit Price | Disc% | Amount | |
| M | FASTENER,WINDSHIELD | nee / | | | 4.00 | 6.00 | 00.00 | 24.00 |
| M | STOPPER,WINDSHIELD GLASS | nee / | | | 2.00 | 3.00 | 00.00 | 6.00 |
| M | DAM, TAILGATE, LWR | nee / | | | 1.00 | 41.00 | 00.00 | 41.00 |
| M | ELECTRIC AUTO TAILGATE | ? | | | 1.00 | 817.00 | 00.00 | 817.00 |
| M | MARK, OUTLANDER | nee / | | | 1.00 | 95.00 | 00.00 | 95.00 |
| M | DECAL, MIVEC | nee / | | | 1.00 | 77.00 | 00.00 | 77.00 |
| M | REINFORCEMENT, RR BUMPER, RH | x ? | | | 1.00 | 79.00 | 00.00 | 79.00 |
| M | REINFORCEMENT, RR BUMPER, LH | x | | | 1.00 | 79.00 | 00.00 | 79.00 |
| M | BRKT, R/BMPR FACE SIDE, LH | x | | | 1.00 | 12.00 | 00.00 | 12.00 |
| M | BRKT, R/BMPR FACE SIDE, RH | h / | | | 1.00 | 12.00 | 00.00 | 12.00 |
| M | FACE, RR BUMPER | de / | | | 1.00 | 807.00 | 00.00 | 807.00 |
| M | EXTENSION, RR BUMPER | cm / | | | 1.00 | 292.00 | 00.00 | 292.00 |
| M | CLIP, FR BUMPER | nee / | | | 4.00 | 4.00 | 00.00 | 16.00 |

Estimate

Estimate

SURVEYOR NAME: Rasul - Hy 90010068SURVEYOR SIGNATURE: [Signature]DATE: 26/06/2020 @ 1010REMARKS: 6 daysResey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

| | | |
|----------------------|----------|------------------|
| 7% GST on | 11250.00 | 11,250.00 |
| | | 787.50 |
| Total Payable | | 12,037.50 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or in the event of inadvertent breakage in the course of renewing of the windscreen.