

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 38298

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0437/2020/NS
Date : 20-Jun-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Rasul

5 days - ok - jb - `11 Aug 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Soma Saharay
Address : 9 Serangoon Ave 2
#10-25
Singapore 556134
Telephone : HP +65 97267223
Type of Claim : Own Damage Claims
Policy No. : 1800103767
Vehicle No : **SME 3282 C**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Sep-18
Engine No : CVK 064775
Chassis No : WAUZZZF4XJN015621
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Jun-20
Place of Accident : North Buona Vista Rd Near Holland Rd Crossing

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 3282 C

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer Assy and front parking	S/N \$	480.00	\$ 480.00
2	To remove and renew aircon condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	\$ 1,200.00
3	To dismantle and renew front bumper, bonnet, and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. (Both headlamp replaced)	\$	4,900.00	\$ 1,500.00
4	To respray front bumper, bonnet and hinges.	\$	2,500.00	\$ 1,100.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 9,272.00	\$ 4,472.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 3282 C

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
1	FRONT BUMPER		\$ 2,068.00	\$ 1,654.40
2	FRONT BUMPER FIXING PARTS		\$ 269.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 67.00	
4	FRONT BUMPER GRILLE - CENTRE		\$ 185.00	\$ 148.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 198.00	
6	RADIATOR GRILLE		\$ 1,254.00	\$ 1,003.20
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 254.00	
8	FRONT BUMPER CARRIER		\$ 757.00	\$ 605.60
9	FRONT BUMPER FOAM FILLER PIECE		\$ 117.00	\$ 93.68
10	FRONT BUMPER COVER		\$ 120.00	\$ 96.00
11	CAUTION SIGN STICKER	NEC	\$ 13.00	\$ 10.40
12	AIRCON STICKER	NEC	\$ 7.00	\$ 5.60
13	LOCK CARRIER BRACKET		\$ 129.00	\$ 103.20
14	FRONT BUMPER SUPPORT - LH / RH	2	\$ 54.00	
15	FRONT PARKING AID SENSOR - INNER / OUTER	2	TBC	
16	FRONT PARKING AID SEAL RING	4	\$ 14.00	
17	HORN - LH HIGH TONE		\$ 119.00	
18	HORN - RH LOW TONE		\$ 119.00	
19	SPRING SHACKLE - LH / RH	2	\$ 54.00	
20	BONNET		\$ 2,634.00	\$ 2,107.20
SUB TOTAL SPARE PARTS CHARGES			\$ 8,432.00	\$ 5,827.28

Telefax

Material List for Accident Vehicle Regn No. SME 3282 C

		Damage Parts & Prices		
S/N	Parts Description		S/Nett	Remarks
		<i>c/f</i>		\$ 5,827.28
21	BONNET ATTACHMENT PARTS		\$ 115.00	
22	BONNET LID HINGE - LH / RH	2	\$ 574.00	
23	BONNET IMPACT PROTECTION - CENTRE/LH/RH	3	\$ 78.00	\$ 62.40
24	BONNET STRIKER - LH / RH	2	\$ 94.00	
25	BONNET LID LOCK	2	\$ 403.00	
26	BONNET BOWDEN CABLE - CENTRE		\$ 54.00	
27	BONNET BOWDEN CABLE		\$ 54.00	
28	BONNET RELEASE LEVER		\$ 13.00	
29	BONNET SOUND ABSORBER		\$ 323.00	
30	WHEEL SPOILER - LH / RH	2	\$ 138.00	
31	WHEEL SPOILER TRIM - LH		\$ 33.00	
32	WHEEL SPOILER TRIM - RH		\$ 34.00	
33	LED HEADLIGHT - LH / RH	2	\$ 14,642.00	\$ 11,713.60
34	LIFT CYLINDER - LH / RH	2	\$ 396.00	
35	LIFT CYLINDER CORRUGATED PIPE		\$ 88.00	
36	TEMPERATURE SENSOR BRACKET		\$ 18.00	\$ 14.40
37	CHARGE AIR COOLER		\$ 552.00	\$ 441.60
38	AIRCON CONDENSER		\$ 586.00	\$ 468.80
39	LOCK CARRIER		\$ 956.00	
40	READY MIX COOLANT		\$ 86.00	
41	AIR GUIDE - LH / RH	2	\$ 54.00	\$ 21.60
42	AIR GUIDE - LH / RH	2	\$ 24.00	\$ 9.60
43	AIR GUIDE - UPPER		\$ 15.00	
44	AIR GUIDE - LOWER		\$ 21.00	
45	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
46	ADDED PARTS - SEE ATTACHED		\$ 214.00	\$ 171.20
47	SUNDRIES		\$ 200.00	\$ 51.84
TOTAL SPARE PARTS CHARGES		:	\$ 28,257.00	\$ 18,842.32
TOTAL LABOUR CHARGES		:	\$ 9,272.00	\$ 4,472.00
GRAND TOTAL		:	\$ 37,529.00	\$ 23,314.32

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0437/2020/NS 13-Jul-20 Glory Tan 1 OF 1 SME 3282 C Audi A4 Sedan 2.0 TFSI 8W
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Front bumper reinforcement bracket RHS	\$ 214.00	\$ 171.20
TOTAL		\$ 214.00	\$ 171.20

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant