

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20006547/UBS3Q2

Date: 12/08/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00008898-01

Claimant
Vehicle No : SMF367G **Insured Vehicle No :** SKK4348H

Date of Loss: 21/06/2020 Nature of Claim: TP Claim No: 1202000018617

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF367G		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI COD S-TRONIC (A)	Engine No:	CZE802018
Reg. Date:	25/10/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V3J1082087
Colour:	Red	Odometer:	32431 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,214.27	8,607.48	13,606.79	61.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,730.00	2,410.00	2,320.00	49.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,944.27	11,017.48	15,926.79	59.11
Approved Total (Overridden) (S\$)		8,800.00		
Nett Amount (S\$)	26,944.27	8,800.00	18,144.27	67.34
+ Car Rental (7.0 x S\$140.00/day) (S\$)		980.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		9,816.45		
Global Sum Settlement (S\$)		9,800.00		

INSPECTION

Date of Assignment: 23/06/2020

Date Inspected: 23/06/2020 Inspected At:

Nineteen Autowerks Pte Ltd (HQ)
BLK 15 KAKI BUKIT ROAD 4 #01-53
BARTLEY BIZ CENTRE
Singapore 417808

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2020)
Parts:	143	AUDI A3 1.4 SEDAN TFSI COD S-TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF367G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET	Repair	1,334.00 FL	*- FL
2	1	*FRONT BONNET LOCK	Not Necessary	238.00 FL	*- FL
3	1	*FRONT BONNET RUBBER	Not Necessary	80.00 FL	*- FL
4	1	*FRONT HEADLAMP N/S	Cracked	3,320.00 FL	*3,320.00 FL
5	1	*FRONT HEADLAMP LOWER BRACKET N/S	Not Necessary	198.00 FL	*- FL
6	1	*FRONT GRILLE WITH CHROME MOULDING	Cracked	583.00 FL	*583.00 FL
7	1	*FRONT GRILLE LOGO	Not Necessary	101.20 FL	*- FL
8	1	*FRONT BUMPER	Deformed / Torn	1,665.40 FL	*1,512.20 FL
9	1	*SET FRONT BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
10	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	598.40 FL	*- FL
11	1	*FRONT BUMPER SPONGE	Torn	184.80 FL	*145.50 FL
12	2	*FRONT BUMPER SIDE RETAINERS	Not Necessary	68.00 FL	*- FL
13	1	*REAR BOOT LID	Repair	1,932.00 FL	*- FL
14	2	*REAR BOOT HINGES	Not Necessary	552.00 FL	*- FL
15	2	*REAR BOOT LAMPS	Not Necessary	1,262.00 FL	*- FL
16	1	*REAR BOOT LOCK	Not Necessary	295.00 FL	*- FL
17	1	*REAR BOOT LOGO	Necessary	115.00 FL	*93.20 FL
18	1	*REAR BOOT RUBBER	Not Necessary	175.20 FL	*- FL
19	1	*REAR BOOT A3 EMBLEM	Necessary	70.00 FL	*70.00 FL
20	1	*REAR BOOT TFSI EMBLEM	Necessary	86.40 FL	*71.00 FL
21	2	*REAR TAILLAMPS	Not Necessary	1,516.00 FL	*- FL
22	1	*REAR END PANEL	Dented	660.00 FL	*660.00 FL
23	1	*REAR END PANEL INNER GARNISH	Not Necessary	242.00 FL	*- FL
24	1	*REAR BUMPER	Deformed	1,325.00 FL	*1,325.00 FL
25	1	*REAR BUMPER INNER SPONGE	No such part	180.00 FL	*- FL
26	1	*REAR BUMPER LOWER DIFFUSER	Deformed / Torn	743.00 FL	*495.00 FL
27	1	*REAR BUMPER REINFORCEMENT	Dented	455.00 FL	*455.00 FL
28	2	*REAR BUMPER REINFORCEMENT STAYS	Not Necessary	312.00 FL	*- FL
29	2	*REAR BUMPER SIDE RETAINERS	Not Necessary	136.00 FL	*- FL
30	2	*REAR BUMPER REFLECTORS	Not Necessary	190.00 FL	*- FL
31	4	*REAR BUMPER PDC SENSORS	Shorted (1 PCS ONLY)	3,072.00 FL	*196.40 FL
32	1	*REAR EXHAUST SILENCER	Not Necessary	1,344.00 FL	*- FL
33	2	*REAR EXHAUST MOUNTINGS	Not Necessary	163.20 FL	*- FL
34	1	*FRONT NUMBER PLATE WITH HOLDER	Cracked	80.00 FS	*40.00 FS
35	1	*SET REAR BUMPER CLIP	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,376.60	9,056.30
- List Item Discount on L Items 5.00/5.00% (\$\$)	1,162.33	448.82
Total Parts (\$\$)	22,214.27	8,607.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING }	New	80.00	30.00
2	TO REMOVE,REPLACED DAMAGED LAMP AND CHECK UP REAR WIRING }	New	80.00	0.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
5	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	0.00
6	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
7	TO APPLY UNDERCOATING	New	200.00	50.00
8	PANEL BEATING	New	2,000.00	1,000.00
9	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,800.00	1,200.00
Gross Labour Cost (\$\$)			4,730.00	2,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >