



NINETEEN
AUTOWERKS

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
Bartley Blz Centre, Singapore 417807
Tel: (65) 9270 5882
nineteenautowerks@gmail.com

not Authorized

23 June 2020

ACCIDENT DATE: 21 JUNE 2020
OWNER: KOH ZHAN YU
REG NO.: SMF 367 G
MAKE/MODEL: AUDI A3

Like Jasper
FWD

23/6/20
2/5 8800/
Wh. ph. After rep. 7 days.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Front bonnet	\$ 12 1,334.00 X
1	Front bonnet lock	\$ 11 238.00 X
1	Front bonnet rubber	\$ 11 80.00 X
1	Front headlamp 1/1	\$ Cne 3,320.00 ✓
1	Front headlamp lower bracket 1/1	\$ 11 198.00 X
1	Front grille with chrome moulding	\$ Cne 583.00 ✓
1	Front grille logo	\$ 11 101.20 X
1	Front bumper 1512.20	\$ De/To. 1,665.40 ✓
1	Front bumper clip (1 set)	\$ 11 50.00 ✓
1	Front bumper reinforcement	\$ 11 598.40 X
1	Front bumper sponge 145.50	\$ 700 184.80 ✓
2	Front bumper side retainers	\$ 11 68.00 X
1	Rear boot lid	\$ 12 1,932.00 X
2	Rear boot hinges	\$ 11 552.00 X
2	Rear boot lamps	\$ 11 1,262.00 X
1	Rear boot lock	\$ 11 295.00 X
1	Rear boot logo 93.20	\$ 11 115.00 ✓
1	Rear boot rubber	\$ 11 175.20 X
1	Rear boot "A3" emblem	\$ 11 70.00 ✓
1	Rear boot "TFSI" emblem 71.00	\$ 11 86.40 ✓
2	Rear taillamps	\$ 11 1,516.00 X
1	Rear end panel	\$ 11 660.00 ✓
1	Rear end panel inner garnish	\$ 11 242.00 X
1	Rear bumper	\$ De 1,325.00 ✓
1	Rear bumper inner sponge	\$ 11 180.00 X
1	Rear bumper lower diffuser 495.00	\$ De/To. 743.00 ✓
1	Rear bumper reinforcement	\$ 11 455.00 ✓
2	Rear bumper reinforcement stays	\$ 11 312.00 X
2	Rear bumper side retainers	\$ 11 136.00 X
2	Rear bumper reflectors	\$ 11 190.00 X
4	Rear bumper PDC sensors 196.40	\$ 300 3,072.00 1pc
1	Rear exhaust silencer	\$ 11 1,344.00 X
2	Rear exhaust mountings	\$ 11 163.20 X
		\$ 23,246.60
	Less 5%	\$ 1,162.33
		\$ 22,084.27

	<u>SPECIAL NETT ITEMS</u>
1	Front number plate with holder
1	Rear bumper clip (1 set)

\$	CN	80.00	40
\$	RM	50.00	40
\$		130.00	

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.
2	To remove, replaced damaged lamps and check up rear wiring.
3	To remove and refit inner garnishes.
4	To remove and refit rear reverse sensor.
5	To transfer boot lid mechanism and wiring assembly.
6	To remove, refit and replace exhaust silencer and mountings.
7	To apply undercoating.
8	Panel beating.
9	To re-spray painting on the affected areas.

\$		80.00	
\$		80.00	30
\$		150.00	80
\$		150.00	50
\$	11	120.00	X
\$	11	150.00	X
\$		200.00	50
\$		2,000.00	1000
\$		1,800.00	1200
\$		4,730.00	

GRAND TOTAL :

\$	26,944.27
----	------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-8976.30
52
P-8527.48
S.N-80.00
L-2410.00
11017.48
202
2813.98