

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 22.06.2020

Accident Date : 21.04.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Mercedes Benz E220D " Reg. No. SBR7M Claiming Against Your Insured Reg. No. SCP3939C		
1pc	Rear Door RH		B 2,470.00 ✓
1pc	Rear Door Weatherstrip		M 398.00 ✓
1pc	Rear Door Sticker		M 75.00 ✓
1pc	Rear Door Inner Insulation		165.00 ?
14pcs	Rear Door Panel Rivets	6.00	M 60.00 ✓
1pc	Rear Door Frame Rubber Seal		M 105.00 ✓
			3,273.00
	Less 10%		327.30
			2,945.70
	To Conduct Electrical Check		30.00 201
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		M 80.00 X
	To Dismantle / Transfer Door Fittings / Ancillary Accessories		160.00 601
	Labour Charge - Panel Beating, Repairing Of Rear Fender Arch Panel, Rocker Skirt, and Parts Replacement		400.00 2501
	To Respray Affected Areas		6001 1,000.00
	To Reseal Paint Protection (Diamondbrite) to Spray Paint Areas		450.00 ?
		Total :	5,065.70

*Not Authorised
Respray B4 paint
3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: