



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. NA2003398
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE
SINGAPORE 189556

INV Date 29/06/2020
Reference NS/INC20006556/T1qf3n2
Code INC4



PROFESSIONAL SERVICE FEE

Vehicle No. SHC 2352K
Insured Veh. SML 8523M
Claim No. MT/1094878-002
Policy No. 5115012680
Accident Date 22/06/2020
Inspection Date 22/06/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'National Assessment Centre Services'

National Assessment Centre Services

HYN




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20006556/T1qf3n2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 29-06-2020	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SML 8523M	Veh. Inspected	SHC 2352K	
Policy No.	5115012680	Coverage (\$)	0.00	
Claim No.	MT/1094878-002	Excess (\$)	0.00	
Assign From		Assign Date	22/06/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU903077835	Colour	BLUE	
Odometer	208977	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	SATURN	6 mm	
L/H Front Tyre	195/65 R15	SATURN	6 mm	
R/H Rear Tyre	195/65 R15	SATURN	6 mm	
L/H Rear Tyre	195/65 R15	SATURN	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	22/06/2020	Inspection Date	22/06/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2352K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER FRONT BUMPER	DEFORMED	499.90	499.90
1	COVER FRONT BUMPER HOLE R	MISSING	28.38	28.38
1	HOOD SUB-ASSY	BENT	950.50	950.50
1	FENDER SUB-ASSY FRONT RH	BENT	933.10	933.10
1	EMBLEM SIDE PANEL (HYBRID)	NECESSARY	86.00	86.00
1	LAMP ASSY FOG RH	CRACKED	920.00	920.00
1	UNIT ASSY HEADLAMP RH	CRACKED	3,455.00	3,455.00
1	REINFORCEMENT SUB-ASSY FR	NOT NECESSARY	696.40	-
1	GRILLE SUB-ASSY RADIATOR	NOT NECESSARY	438.00	-
1	SUPPORT FRONT BUMPER SIDE	DEFORMED	76.90	76.90
1	SUPPORT RADIATOR UPPER RH	TO REPAIR SEE LABOUR	76.10	-
1	SUPPORT SUB-ASSY RADIATOR	NOT NECESSARY	234.70	-
1	SUPPORT SUB-ASSY RADIATOR	NOT NECESSARY	361.10	-
1	GRILLE RADIATOR LOWER NO	NOT NECESSARY	163.40	-
1	EMBLEM ASSY RADIATOR GRIL	NOT NECESSARY	88.00	-
1	COVER ENGINE UNDER COVER	NOT NECESSARY	180.00	-
1	ENGINE UNDER COVER NO 1	NOT NECESSARY	457.40	-
	LESS 25% DISCOUNT		-2,411.22	-1,737.47
			7,233.66	5,212.31
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF SUPPORT RADIATOR UPPER RH.		1,000.00	640.00
	SPRAYPAINT CHARGE.		800.00	600.00
	CHECK ALL LIGHTING.		50.00	30.00
	TO VAC & TOP UP A/C GAS.	NOT NECESSARY	120.00	-
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
			2,020.00	1,300.00
GRAND TOTAL			9,253.66	6,512.31
RECOMMENDED COST OF REPAIRS (CONFIRMED)				6,512.31

Report Ref No. NS/INC20006556/T1qf3n2

Report Ref No. NS/INC20006556/T1qf3n2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHC 2352K

INSPECTION





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHC 2352K

RE-INSPECTION

