

REC. BY:

REF: QBE1

ASSIGNMENT

ASS. REC. BY:

REF: AIG1

Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/P 91082728

Tay Lay Har Irene
Blk 348B #08-565
Yishun Ave 11
Singapore 762348

Vehicle No : SLP 9066 A
Make : Mitsubishi Lancer
Year : 2017

Not Authorized
C/Sing \$11,500h
Recovery After Paint

8 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear boot lid
1 pc	Rear o/s boot lid hinge
1 pc	Rear o/s boot damper
1 pc	Rear boot lid inner lock
1 pc	Rear boot lid outer lock
1 pc	Rear boot lid emblem " Logo "
1 pc	Rear boot lid emblem " Lancer "
2 pcs	Rear no plate lamp
1 pc	Rear boot rubber
1 pc	Rear end panel
1 pc	Rear end panel inner garnish
1 pc	Rear o/s tail-lamp assy
1 pc	Rear o/s tail-lamp lower bracket
1 pc	Rear o/s tail-lamp panel
1 pc	Rear o/s fender inner trim
1 pc	Rear bumper
1 pc	Rear bumper reinforcement
1 pc	Rear o/s bumper side retainer
1 pc	Rear bumper tow cover
1 pc	Rear o/s bumper reflector
1 pc	Rear spare tyre cover board
1 pc	Rear exhaust silencer
1 pc	Front n/s shock absorber
1 pc	Front n/s lower arm
1 pc	Front n/s knuckle arm
1 pc	Front n/s knuckle bearing
1 pc	Front stabiliser bar
1 pc	Front n/s linkage
1 pc	Steering rack and pinion
1 pc	Steering rack cross member
1 pc	Front n/s drive shaft

Bl	\$755.00	—
DI	\$95.00	—
Sn	\$105.00	X
NI	\$155.00	—
Sn	\$105.00	X
NI	\$48.00	—
NI	\$55.00	—
Sn	\$96.00	X
77-501N	\$48.00	—
CI	\$155.00	501N
R	\$550.00	—
DI	\$175.00	—
NI	\$455.00	—
DI	\$55.00	—
R	\$205.00	—
DI	\$355.00	—
R	\$685.00	—
R	\$487.00	—
DI	\$65.00	—
NI	\$45.00	—
CNI	\$87.00	—
NI	\$195.00	—
R	\$550.00	—
DI	\$385.00	—
R	\$405.00	—
R	\$455.00	—
NI	\$155.00	—
Sn	\$195.00	X
DI	\$85.00	—
R	\$2,250.00	—
Bl	\$565.00	—
R	\$950.00	—
balance c/f	\$10,923.00	

1830

REF: Q021

ASSIGNMENT

REF: AIG/

0066 A

balance b/f \$10,923.00

- 1 pc Front engine under cover
 2 pcs Rear shock absorber
 2 pcs Rear lower arm
 2 pcs Rear upper arm
 2 pcs Rear trailing arm
 2 pcs Rear hub assy
 2 pcs Rear hub bearing
 2 pcs Rear knuckle arm

N/S A
 N/S D/S

	\$175.00	X
	\$650.00	X
	\$325.00	X
	\$375.00	X
	\$205.00	X
	\$225.00	X
	\$385.00	X
	\$125.00	X
	\$397.00	X
	\$794.00	X
	\$15,172.00	
Less 10 %	\$1,517.20	
	\$13,654.80	

S. Nett Item

- 1 pc Front n/s rim
 1 pc Rear no plate
 1 set Rear reverse sensor
 20 pcs Clip

	\$450.00	X
	\$45.00	X
	\$200.00	X
\$2.00	\$40.00	X
	\$735.00	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,000.00

To putty & spray paint on rear accident affected portion.

\$1,000.00

Check/reconnect wiring.

\$45.00

To spray anti rust on accident affected portion.

\$180.00

Remove/renew rear exhaust silencer.

\$180.00

Towing fee

(\$110) \$160.00

Remove/renew both front and rear undercarriages

\$750.00

Check and realign wheel alignment

\$60.00

Remove/refit rear boot upholstery to facilitate repair

\$100.00

Total \$17,864.80

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: