

ASS. REC. BY:

REF:

AIG/200065691Kg

Merach

## ASSIGNMENT

From:

Date:

Estimated Cost:

OO/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 2100090379

Claims No. 5390872279SG

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Sal. or Market Value:

IDAC Accident Report

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Kenneth confirmed LS \$11500, 8 days.

(Red \$6364.80, 36%)

Date/Time, File Pass to?

☐

: Prel. Report

11/24/07 Typist

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

8

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format: MER-TP

Lump Sum + H.D. \$ 11500

Veh No: SUP 9066A Yr Regn: 06, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M7 Lancer

c.c

1590

Colour

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

168.365

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

JMYSPER Y AIGU 006673

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / A/Rlm or

Tyre Size:

F:

R:

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

R/Bal.

P

mm

Rear

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

22/6/20

D.O.I.

24/6/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

# Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225  
H/P 91082728

Tay Lay Har Irene  
Blk 348B #08-565  
Yishun Ave 11  
Singapore 762348

Vehicle No : SLP 9066 A  
Make : Mitsubishi Lancer  
Year : 2017

*Not Authorised*  
*61 Sing & ?*  
*Resony After Pain*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate Cost Of Repair

1 pc	Rear boot lid	<i>Alu</i> \$755.00	<i>—</i>
1 pc	Rear o/s boot lid hinge	<i>D/I</i> \$95.00	<i>—</i>
1 pc	Rear o/s boot damper		<i>?</i>
1 pc	Rear boot lid inner lock	<i>NU</i> \$155.00	<i>✓</i>
1 pc	Rear boot lid outer lock	<i>Sm</i> \$105.00	<i>X</i>
1 pc	Rear boot lid emblem " Logo "	<i>nu</i> \$48.00	<i>—</i>
1 pc	Rear boot lid emblem " Lancer "	<i>nu</i> \$55.00	<i>—</i>
2 pcs	Rear no plate lamp	\$48.00 \$96.00	<i>?</i>
1 pc	Rear boot rubber	<i>CUA</i> \$155.00	<i>50/50</i>
1 pc	Rear end panel	<i>Ry</i> \$550.00	<i>—</i>
1 pc	Rear end panel inner garnish	<i>D/I</i> \$175.00	<i>—</i>
1 pc	Rear o/s tail-lamp assy	<i>my CRT</i> \$455.00	<i>—</i>
1 pc	Rear o/s tail-lamp lower bracket	<i>D/I</i> \$55.00	<i>—</i>
1 pc	Rear o/s tail-lamp panel		<i>?</i>
1 pc	Rear o/s fender inner trim		<i>?</i>
1 pc	Rear bumper	<i>Ry</i> \$355.00	<i>—</i>
1 pc	Rear bumper reinforcement	<i>Ry</i> \$685.00	<i>—</i>
1 pc	Rear o/s bumper side retainer	<i>D/I</i> \$487.00	<i>—</i>
1 pc	Rear bumper tow cover	<i>NU</i> \$65.00	<i>—</i>
1 pc	Rear o/s bumper reflector	<i>CNA</i> \$45.00	<i>—</i>
1 pc	Rear spare tyre cover board	<i>nu</i> \$87.00	<i>—</i>
1 pc	Rear exhaust silencer	<i>Ry</i> \$195.00	<i>—</i>
1 pc	Front n/s shock absorber		<i>?</i>
1 pc	Front n/s lower arm		<i>?</i>
1 pc	Front n/s kunckle arm	<i>Ry</i> \$405.00	<i>—</i>
1 pc	Front n/s kunckle bearing	<i>nu</i> \$455.00	<i>—</i>
1 pc	Front stabiliser bar		<i>?</i>
1 pc	Front n/s linkage		<i>?</i>
1 pc	Steering rack and pinion		<i>?</i>
1 pc	Steering rack cross member		<i>?</i>
1 pc	Front n/s drive shaft		<i>?</i>
		balance c/f	\$10,923.00



SLP 9066 A

balance b/f \$10,923.00

1 pc	Front engine under cover
2 pcs	Rear shock absorber
2 pcs	Rear lower arm
2 pcs	Rear upper arm
2 pcs	Rear trailing arm
2 pcs	Rear hub assy
2 pcs	Rear hub bearing
2 pcs	Rear knuckle arm

NLS B

O/S ?

	\$175.00	X
	\$650.00	?
	\$375.00	7
	\$205.00	410.00
	\$225.00	450.00
	\$385.00	770.00
	\$125.00	250.00
	\$397.00	794.00
		\$15,172.00
Less 10 %		\$1,517.20
		\$13,654.80

S. Nett Item

1 pc	Front n/s rim
1 pc	Rear no plate
1 set	Rear reverse sensor
20 pcs	Clip

	\$450.00	300.00
	\$45.00	—
	\$200.00	—
\$2.00	\$40.00	—
		\$735.00

Labour Charges

Remove/renew the above parts including knocking, welding &amp; cutting.

\$1,000.00 800

To putty &amp; spray paint on rear accident affected portion.

\$1,000.00 800

Check/reconnect wiring.

\$45.00 200

To spray anti rust on accident affected portion.

\$180.00 600

Remove/renew rear exhaust silencer.

\$180.00 600

Towing fee

(B.II) \$160.00 ✓

Remove/renew both front and rear undercarriages

\$750.00 4800

Check and realign wheel alignment

\$60.00 ✓

Remove/refit rear boot upholstery to facilitate repair

\$100.00 800

Total \$17,864.80

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/06/2020 14:44
Date Of Accident	22/06/2020 13:00
Exact Location Of Accident	BRADDELL RD SLIP RD INTO UPP SERANGOON RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP9066A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAY LAY HAR IRENE (ZHENG LIXIA IRENE)
NRIC No	SXXXX584H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91771069
Alternative Phone No	OFFICE-91771069

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104241540-01
Cover Note Number	

### Driver

Name of Driver	LEE WAI KIT (LI WEIJIE)
NRIC No	SXXXX999B
Date Of Birth	29/05/1981
Occupation	OUTDOOR
Date Of Driving Pass	18/06/2011
Driving Experience	9 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84827505
Fax Number	
Contact Number	
EMail Address	NOEMAIL



BLK 348B YISHUN AVE 11 #08-565

762348

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions RAINING

Road Surface WET

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Passenger 1 NAME: : UNKNOWN

GENDER: : MALE

Passenger 2 NAME: : UNKNOWN

GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: WITH DRIVER

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJH4879U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver PAUL PERINBANATHAN ANBUNATHAN SAMUEL STANLEY

NRIC/Passport Number SXXXX145D

Contact Number

Address

ASS.  
Ken LAM

Upp Serangoon Rd

A = SLP 90661A

B = SJH 4879U



Brundell Rd

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was waiting at the give way junction, waiting for main road traffic to clear suddenly behind vehicle hit onto my rear portion. Due to the great impact my car run up onto the kerb.

After the accident I feel uncomfortable on my neck

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 22 June 2020 / 1430

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GIAPMC SketchPlanForm\_V3