



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 9898T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BOOTLID (CONSISTENT)	DENTED	883.20	690.00
1	BOOTLID LOCK (CONSISTENT)	DAMAGED	285.00	115.00
1	BOOTLID W/STRIP (CONSISTENT)	CUT	243.00	187.00
1	CIVIC EMBLEM (CONSISTENT)	NECESSARY	42.50	42.50
1	H EMBLEM (CONSISTENT)	NECESSARY	36.00	36.00
2	BOOTLID REFLECTOR (CONSISTENT)	CUT	487.20	487.20
2	TAILLAMP (CONSISTENT)	N/S CUT / O/S CRACKED	696.40	598.00
1	REAR BUMPER (CONSISTENT)	DISTORTED	638.00	638.00
2	REAR BUMPER RETAINER (CONSISTENT)	NECESSARY	167.00	46.00
8	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	36.00	36.00
1	END PANEL (CONSISTENT)	DENTED	733.20	316.00
1	END PANEL INNER GARNISH (CONSISTENT)	DEFORMED	247.00	96.00
2	REAR FENDER INNER TRIM (CONSISTENT)	NOT NECESSARY	92.40	-
1	SPARE TYRE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	971.00	-
1	SPARE TYRE CARDBOARD (CONSISTENT)	DEFORMED	297.00	297.00
	LESS 20% DISCOUNT		-1,170.98	-716.94
			4,683.92	2,867.76
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	250.00	200.00
1	REAR NO PLATE (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
			290.00	200.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL .		1,400.00	1,000.00
	SPRAY PAINTING.		1,400.00	800.00
	WIRING .		30.00	30.00
	RUST PROOFING .		80.00	80.00
	UPHOLSTERY .		120.00	60.00
			3,030.00	1,970.00

Report Ref No. CC4/ASM20006576/Aba3q2



GRAND TOTAL		8,003.92	5,037.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,500.00

Report Ref No. CC4/ASM20006576/Aba3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.