

# J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,  
Defu Industrial Park C, Singapore 539186  
Tel : 6343-0934 Fax : 6343-0921  
Email : jmartauto@gmail.com  
Registration No: 201400246D  
GST Reg. No: 201400246D

23-Jun-20

Our ref : TP/4848/20

Chua Lay Khim

TP AYX  
Jasper

JHMF0163065210556

## RE : estimate cost for vehicle no : SGV 9898T

|       |                                      |             |          |   |      |
|-------|--------------------------------------|-------------|----------|---|------|
| 1 pc  | bootlid <i>Deled</i>                 | \$          | 883.20   | ✓ | 690  |
| 1 pc  | bootlid lock <i>and</i>              |             | 285.00   | ✓ | 115  |
| 1 pc  | bootlid w/strip <i>cut</i>           |             | 243.00   | ✓ | 187  |
| 1 pc  | Civic emblem <i>new</i>              |             | 42.50    | ✓ |      |
| 1 pc  | H emblem                             |             | 36.00    | ✓ |      |
| 2 pcs | bootlid reflector <i>cut</i>         |             | 487.20   | ✓ |      |
| 2 pcs | taillamp <i>LH cut, RH covered</i>   |             | 696.40   | ✓ | 598  |
| 1 pc  | rear bumper <i>Distorted</i>         |             | 638.00   | ✓ |      |
| 2 pcs | rear bumper retainer <i>new</i>      |             | 167.00   | ✓ | 46.  |
| 8 pcs | rear bumper clips <i>new</i>         |             | 36.00    | ✓ |      |
| 1 pc  | end panel <i>Deled</i>               |             | 733.20   | ✓ | 316. |
| 1 pc  | end panel inner garnish <i>Deled</i> | 3584.70     | 247.00   | ✓ | 86.  |
| 2 pcs | rear fender inner trim <i>new</i>    |             | 92.40    | ✓ |      |
| 1 pc  | spare tyre panel <i>Repair</i>       | 2867.76     | 971.00   | ✓ |      |
| 1 pc  | spare tyre cardboard <i>Deled</i>    |             | 297.00   | ✓ |      |
|       |                                      |             | 5,854.90 |   |      |
|       |                                      | less 20%    | 1,170.98 |   |      |
|       |                                      |             | 4,683.92 |   |      |
| 1 pc  | reverse sensor <i>Deled</i>          | 200         | 250.00   | ✓ | 200  |
| 1 pc  | rear no plate <i>new</i>             |             | 40.00    | ✓ |      |
|       | Panel beating.                       |             | 1,400.00 | ✓ | 1000 |
|       | Spray painting.                      |             | 1,400.00 | ✓ | 800  |
|       | Wiring.                              | 1570        | 30.00    | ✓ |      |
|       | Rust proofing.                       |             | 80.00    | ✓ |      |
|       | Upholstery.                          |             | 120.00   | ✓ | 60   |
|       |                                      |             | 8003.92  |   |      |
|       |                                      | Plus 7% GST | 560.27   |   |      |
|       |                                      |             | 8564.19  |   |      |

SD : Eight thousand five hundred sixty-four & cents nineteen only.

total: 5037.76 Admin  
L/S : 3.5K L/S 23/06/20  
(Nett Value)  
88 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: