

**MOVA**

Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/04
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

23/06/2020

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1

Veh # :- SGE8885B

Veh Model :- NISSAN SUNNY 1.6EX A

Estimate# :- CK420738

Claim # :-

ACC. Date :- 20/06/20

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
NET ITEMS :				
1.	REAR BOOT <i>bt</i>	1 PC	745.20	745.20
2.	REAR BOOT LOGO <i>nee</i>	1 PC	64.70	64.70
3.	REAR BOOT EMBLEM "SUNNY" <i>nee</i>	1 PC	68.30	68.30
4.	REAR BOOT EMBLEM "EX SALOON" <i>nee</i>	1 PC	68.30	68.30
5.	REAR BOOT EMBLEM "CVTC" <i>nee</i>	1 PC	65.50	65.50
6.	REAR BOOT EMBLEM "E-THROTTLE" <i>nee</i>	1 PC	65.50	65.50
7.	REAR BOOT CHROME TOP <i>XSVL</i>	1 PC	171.20	171.20 X
8.	REAR BOOT CHROME LOWER <i>XSVL</i>	1 PC	165.30	165.30 X
9.	REAR BOIOT CHROME CLIPS <i>nee</i>	8 PC	5.90	47.20
10.	REAR BOOT LOCK TOP <i>XSVL</i>	1 PC	114.20	114.20 X
11.	REAR BOOT LOCK LOWER <i>XSVL</i>	1 PC	76.50	76.50 X
12.	REAR BOOT RUBBER <i>Town</i>	1 PC	177.20	177.20
13.	REAR LAMP L+R <i>LH-CR (1pc)</i>	1 PC	299.70	599.40 X
14.	REAR LAMP PANEL LH <i>repair</i>	1 PC	114.20	114.20 X
15.	REAR LAMP CLIPS LH <i>nee</i>	1 PC	5.90	11.80
16.	REAR END PANEL <i>bt</i>	1 PC	398.20	398.20
17.	REAR END PANEL GARNISH <i>XSVL</i>	1 PC	171.50	171.50 X
18.	REAR PANEL TRIM <i>XSVL</i>	1 PC	169.70	169.70 X
19.	REAR BUMPER <i>de</i>	1 PC	595.20	595.20
20.	REAR BUMPER CHROME <i>nee</i>	1 PC	212.10	212.10
21.	REAR BUMPER SPONGE <i>XSVL</i>	1 PC	89.70	89.70 X
22.	REAR BUMPER BRACKET LH <i>nee</i>	1 PC	68.30	68.30
23.	REAR BUMPER INNER BRACKET L+R <i>XSVL</i>	2 PC	44.10	88.20 X
24.	REAR BUMPER RETAINER L+R <i>nee</i>	1 PC	72.60	145.20 X
25.	REAR BUMPER CLIPS <i>nee</i>	10 PC	3.90	39.00
26.	REAR FENDER L+R - REPAIR	1 PC		
NET TOTAL S\$				4,531.60
10% DISCOUNT S\$				-453.16
				4,078.44

SPECIAL NET ITEMS :

1.	REAR BUMPER SENSOR <i>nee</i>	1 PC	200.00	200.00
2.	REAR NUMBER PLATE <i>XSVL</i>	1 PC	45.00	45.00 X
SPECIAL NET TOTAL S\$				245.00

LABOUR :

TO CUT & WELD REAR PANEL. TO REPAIR REAR
FENDER L+R, REAR FLOOR PANEL, REAR CHASSIS
L+R, TO REMOVE & REFIX DAMAGED PARTS,
STRAIGHTEN & REALIGN AFFECTED AREAS

TO SPRAY AFFECTED AREAS

TO REMOVE & REFIX LUGGAGE COMPARTMENT SIDE
GARNISH, SIDE TRIM BOARD CARPET & OTHER
ATTACHMENT PARTS

TO REMOVE & REFIX REVERSE SENSOR & CHECK

700 ~~840.00~~800 ~~850.00~~60 ~~100.00~~

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

23/06/2020

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1 138433
Veh # :- SGE8885B
Veh Model :- NISSAN SUNNY 1.6EX A
Estimate# :- CK420738
Claim # :-
ACC. Date :- 20/06/20
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	WATER SEEPAGE			30 80.00
	TO RUST PROOF AFFECTED AREAS			60.00
	LABOUR TOTAL S\$			1,930.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 6,253.44

GST @ 7 % 437.74

AMOUNT DUE S\$ 6,691.18

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 900 100 68
7 days
L/S
30/06/2020 @ 1100
Ready after repair