

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CTI 20006581/UVF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBH 439C

at Workshop m/s

Tan Lim

of

Insured:

YN 9490E

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

48k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

782C

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: GBH 439C

Yr Regn:

1217

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make: NISSAN NV350

c.c 2488

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

50241

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN/MC2E2620009831

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NH / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

20/6/20

D.O.I.

24/6/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 43558 next 8442

29/6/20 confirmed L/S \$1250 with willian. (Red 4066, 12, 76%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 29/6/20-Typist

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format : Merimen

Lump Sum / I.B.I.: (\$1250)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

CTP Insured's Veh No : YN9450E

Date of Accident : 20 June 2020

Messrs Manston Engineering

Date : 22 June 2020

not Adjust
Lhr
2/5 #1250
4 days
Take photo after repair

Estimate To Repair GBH439C - NISSAN NV350 PANEL VAN 2.5 5AT 5DR EU

Chassis No : JN1MC2E26Z0009831

S/No	Quantity	Description	Amount
		NETT ITEMS	
01	1 pc	o/s rear panel <i>R</i>	\$ 1,973.40
02	1 pc	o/s rear lamp <i>Sin</i>	\$ 209.80
03	1 pc	o/s petrol cover <i>Ref</i>	\$ 95.00
04	1 pc	o/s petrol cover switch <i>shorted</i>	\$ 138.00
05	1 pc	rear bumper <i>R</i>	\$ 690.60
			\$ 3,106.80
		Less 10 %	\$ 310.68
			\$ 2,796.12
		LABOUR & MISC. CHARGES	
01		To check electrical lighting concerned.	\$ 50.00
02		To rust-proofing of the affected areas.	\$ 1150.00
03		Labour to remove and reinstall o/s rear panel window glass with supply sealant.	\$ 120.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00
05		Putty and spray painting of the affected portion.	\$ 1,200.00
			\$ 2,520.00
		Total	\$ 5,316.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-442.80
156852
1254.