

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

23/06/2020

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1

Veh # :- SCM886G

Veh Model :- TOYOTA ESTIMA AERAS 2.4

Estimate# :- CK420740

Claim # :-

ACC. Date :- 22/06/20

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BOOT <i>but</i>	1 PC	1,753.80	1,753.80
2.	REAR BOOT LOGO <i>nee</i>	1 PC	75.20	75.20
3.	REAR BOOT EMBLEM "ESTIMA" <i>nee</i>	1 PC	79.80	79.80
4.	REAR BOOT EMBLEM "AERAS" <i>nee</i>	1 PC	79.20	79.20
5.	REAR BOOT CHROME	1 PC	229.80	229.80
6.	REAR BOOT W/S MOULDING <i>nee</i>	1 SET	211.80	211.80
7.	REAR BOOT LOCK TOP <i>bt</i>	1 PC	490.39	490.39
8.	REAR BOOT LOCK COVER TOP <i>MIS</i>	1 PC	94.30	94.30
9.	REAR BOOT LOCK LOWER <i>X</i>	1 PC	45.90	45.90
10.	REAR BOOT LOCK LOWER COVER <i>X</i>	1 PC	42.80	42.80
11.	REAR BOOT RUBBER <i>cut</i>	1 PC	372.90	372.90
12.	REAR BOOT INNER TRIM <i>de</i>	1 PC	317.20	317.20
13.	REAR BOOT HINGE L+R <i>X</i>	2 PC	69.30	138.60
14.	REAR BOOT INNER HANDLE <i>MIS</i>	1 PC	63.80	63.80
15.	REAR BOOT PUSH BUTTOM <i>?</i>	1 PC	178.60	178.60
16.	REAR BOOT STICKER (WARNING SIGN) <i>nee</i>	1 PC	110.20	110.20
17.	REAR BOOT INNER GROMMET <i>nee</i>	10 PC	7.10	71.00
18.	REAR BOOT LAMP LH <i>?</i>	1 PC	440.90	440.90
19.	REAR LAMP LH <i>X</i>	1 PC	475.80	475.80
20.	REAR END PANEL <i>bt</i>	1 PC	754.70	754.70
21.	REAR END PANEL TRIM TOP <i>de</i>	1 PC	294.80	294.80
22.	REAR END PANEL TRIM LOW <i>con</i>	1 PC	199.50	199.50
23.	REAR END PANEL TRIM CLIPS <i>nee</i>	7 PC	6.50	45.50
24.	REAR SIDE GARNISH L+R <i>de</i>	2 PC	552.70	1,105.40
25.	REAR FLOOR PANEL <i>repair</i>	1 PC	805.90	805.90
26.	REAR FLOOR PANEL CARPET <i>X</i>	1 PC	584.70	584.70
27.	REAR BUMPER <i>de</i>	1 PC	290.00	290.00
28.	REAR BUMPER SPONGE L+R <i>de</i>	2 PC	55.00	110.00
29.	REAR BUMPER TOW COVER LH <i>cut</i>	1 PC	30.00	30.00
30.	REAR BUMPER REFLECTOR LH <i>X</i>	1 PC	55.00	55.00
31.	REAR BUMPER SIDE SHIELD L+R <i>X</i>	2 PC	75.00	150.00
LIST TOTAL S\$				9,697.49
25% DISCOUNT S\$				-2,424.37
				7,273.12
SPECIAL NET ITEMS :				
1.	REAR BOOT SEALANT <i>nee</i>	1 PC	50.00	50.00
2.	REAR BUMPER SENSOR <i>nw</i>	1 PC	200.00	200.00
SPECIAL NET TOTAL S\$				250.00

LABOUR :

TO CUT & WELD REAR END PANEL, REAR FLOOR
PANEL. TO REPAIR REAR FENDER LH & RH, REAR
CHASSIS MEMBER LH & RH. TO REMOVE & REFIX
DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED
AREAS

700 1,100.00

Estimate

23/06/2020

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Page # :- 1 138435
Veh # :- SCM886G
Veh Model :- TOYOTA ESTIMA AERAS 2.4
Estimate# :- CK420740
Claim # :-
ACC. Date :- 22/06/20
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg
Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Attention :- XA025

No.	Description	Qty	U.Price	Amounts S\$
	TO SPRAY AFFECTED AREAS	900	1,000.00	
	TO REMOVE & REFIX REAR W/S GLASS	120	150.00	
	TO REMOVE & REFIX REAR BOOT MECHANISM CHECK & TEST WIPER MOTOR, REAR CENTRE LOCKING POWER LOCK SYSTEM	8 days	60	80.00
	TO REMOVE & REFIX THIRD ROLL CUSHION, SDIE COVER, SAFETY BELT AND OTHER ATTACHMENT PARTS	45	2.00	90.00
	TO REMOVE & REFIX REVERSE SENSOR & CHECK WATER SEEPAGE	23/06/2020 @ 1600	60	80.00
	TO RUST PROOF AFFECTED AREA	60	80.00	
	LABOUR TOTAL S\$			2,590.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 10,113.12

GST @ 7 % 707.92

AMOUNT DUE S\$ 10,821.04

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: