

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3392
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

23/06/2020

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1

Veh # :- SCM886G

Veh Model :- TOYOTA ESTIMA AERAS 2.4

Estimate# :- CK420740

Claim # :-

ACC. Date :- 22/06/20

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	REAR BOOT <i>bue</i> ✓	1	PC	1,753.80	1,753.80 ✓
2.	REAR BOOT LOGO <i>nee</i> ✓	1	PC	75.20	75.20 ✓
3.	REAR BOOT EMBLEM "ESTIMA" <i>nee</i> ✓	1	PC	79.80	79.80 ✓
4.	REAR BOOT EMBLEM "AERAS" <i>nee</i> ✓	1	PC	79.20	79.20 ✓
5.	REAR BOOT CHROME <i>cra</i> ✓	1	PC	229.80	229.80 ✓
6.	REAR BOOT W/S MOULDING <i>nee</i> ✓	1	SET	211.80	211.80 ✓
7.	REAR BOOT LOCK TOP <i>bt</i> ✓	1	PC	490.39	490.39 ✓
8.	REAR BOOT LOCK COVER TOP <i>mis</i> ✓	1	PC	94.30	94.30 ✓
9.	REAR BOOT LOCK LOWER <i>XSVL</i> ✓	1	PC	45.90	45.90 X
10.	REAR BOOT LOCK LOWER COVER <i>XSVL</i> ✓	1	PC	42.80	42.80 X
11.	REAR BOOT RUBBER <i>cut</i> ✓	1	PC	372.90	372.90 ✓
12.	REAR BOOT INNER TRIM <i>de</i> ✓	1	PC	317.20	317.20 ✓
13.	REAR BOOT HINGE L+R <i>XSVL</i> ✓	2	PC	69.30	138.60 X
14.	REAR BOOT INNER HANDLE <i>mis</i> ✓	1	PC	63.80	63.80 ✓
15.	REAR BOOT PUSH BUTTON <i>?cra</i> ✓	1	PC	178.60	178.60 ✓
16.	REAR BOOT STICKER (WARNING SIGN) <i>nee</i> ✓	1	PC	110.20	110.20 ✓
17.	REAR BOOT INNER GROMMET <i>nee</i> ✓	10	PC	7.10	71.00 ✓
18.	REAR BOOT LAMP LH <i>?cra</i> ✓	1	PC	440.90	440.90 ✓
19.	REAR LAMP LH <i>?cra</i> ✓	1	PC	475.80	475.80 ✓
20.	REAR END PANEL <i>bt</i> ✓	1	PC	754.70	754.70 ✓
21.	REAR END PANEL TRIM TOP <i>de</i> ✓	1	PC	294.80	294.80 ✓
22.	REAR END PANEL TRIM LOW <i>cra</i> ✓	1	PC	199.50	199.50 ✓
23.	REAR END PANEL TRIM CLIPS <i>nee</i> ✓	7	PC	6.50	45.50 ✓
24.	REAR SIDE GARNISH L+R <i>de</i> ✓	2	PC	552.70	1,105.40 ✓
25.	REAR FLOOR PANEL <i>repair</i> ✓	1	PC	805.90	805.90 R
26.	REAR FLOOR PANEL CARPET <i>?X torn</i> ✓	1	PC	584.70	584.70 ✓
27.	REAR BUMPER <i>de</i> ✓	1	PC	290.00	290.00 ✓
28.	REAR BUMPER SPONGE L+R <i>de</i> ✓	2	PC	55.00	110.00 ✓
29.	REAR BUMPER TOW COVER LH <i>cut</i> ✓	1	PC	30.00	30.00 ✓
30.	REAR BUMPER REFLECTOR LH <i>?cra</i> ✓	1	PC	55.00	55.00 ✓
31.	REAR BUMPER SIDE SHIELD L+R <i>XSVL</i> ✓	2	PC	75.00	150.00 X

LIST TOTAL S\$

9,697.49

25% DISCOUNT S\$

-2,424.37

7,273.12

SPECIAL NET ITEMS :

1.	REAR BOOT SEALANT <i>nee</i> ✓	1	PC	50.00	50.00 ✓
2.	REAR BUMPER SENSOR <i>nw</i> ✓	1	PC	200.00	200.00 ✓

SPECIAL NET TOTAL S\$

250.00

LABOUR :

TO CUT & WELD REAR END PANEL, REAR FLOOR PANEL. TO REPAIR REAR FENDER LH & RH, REAR CHASSIS MEMBER LH & RH. TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS

700 1,100.00

Estimate

23/06/2020

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1 138435
 Veh # :- SCM886G
 Veh Model :- TOYOTA ESTIMA AERAS 2.4
 Estimate# :- CK420740
 Claim # :-
 ACC. Date :- 22/06/20
 Terms :- C.O.D Days
 Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg
Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	TO SPRAY AFFECTED AREAS	1	900	1,000.00
	TO REMOVE & REFIX REAR W/S GLASS	1	120	150.00
	TO REMOVE & REFIX REAR BOOT MECHANISM CHECK & TEST WIPER MOTOR, REAR CENTRE LOCKING POWER LOCK SYSTEM	8 days	60	80.00
	TO REMOVE & REFIX THIRD ROLL CUSHION, SDIE COVER, SAFETY BELT AND OTHER ATTACHMENT PARTS	4S no photo X photo? 60	100.00	
	TO REMOVE & REFIX REVERSE SENSOR & CHECK WATER SEEPAGE	23/06/2020 @ 1600	60	80.00
	TO RUST PROOF AFFECTED AREA	Reay after repair	60	80.00
	LABOUR TOTAL S\$			2,590.00

1900

E. & O.E

NON-TAX AMOUNT S
 AMOUNT S\$ 10,113.12
 GST @ 7 % 707.92
 AMOUNT DUE S\$ 10,821.04

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



Automotive Pte Ltd

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 199904033G
GST Reg. M2-0088864-2

SUPPLEMENTARY


LONPAC INSURANCE BHD
300 BEACH ROAD
17-04/07 THE CONCOURSE
SINGAPORE 199555

Page : 1
Veh No : SCM886G
Model : TOYOTA ESTIMA
Acc Date : 22-Jun-20
Incharge : KEONG

No	Description	Qty	U.Price	Amt \$
	<u>LABOUR:</u>			
1	TO CERAMIC COATING REAR PORTION <i>see</i>			\$350.00
	LABOUR TOTAL S\$			<u>\$ 800.00</u>

NON-TAX AMOUNTS	\$800.00
GST @ 7%	\$56.00
AMOUNT DUE	<u>\$856.00</u>

Customer's Signature/Co. Stamp


MOVA AUTOMOTIVE PTE LTD