

**Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)**

60 Jalan Lam Huat #03 - 35/36, Singapore (737869)

Tel : 6358 3031 | Fax No : 6694 4929

**FINALIZATION FORM**

**ATTN TO:** LKK / SUN PIN  
Surveyor Name and Company

**Date of Accident :** 20/6/2020

**BILL TO:** INDIA  
TP Insurer

**VEHICLE REG. NO.**

**SGV1627L**

**TYPE OF CLAIM:** TP

**Make / Model :** MAZDA5 SP

**COST OF CLAIMS**

**Parts Cost / List :** \$ 3,069.70

**Supp. Parts :** \$ -

**Special Nett :** \$ 200.00

**Total Parts :** \$ 2,655.76

**Total Labour :** \$ 1,780.00

**TOTAL REPAIR COST :** \$ 4,435.76

|                         |           |                 |
|-------------------------|-----------|-----------------|
| Total Parts Cost/List : | \$        | 3,069.70        |
| Plus / Less : 20%       | \$        | 613.94          |
| <b>Total :</b>          | <b>\$</b> | <b>2,455.76</b> |

|                         |           |                 |
|-------------------------|-----------|-----------------|
| Lump Sum Discount : 20% | \$        | 887.15          |
| <b>Lump Sum Amount:</b> | <b>\$</b> | <b>3,548.61</b> |

**Final Lump Sum Amount :** \$ 3,550.00

**Submitted by / Date :** PAULO

**No. of Repair Days:** 4

**Confirmed by / Date :** \_\_\_\_\_

**Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)**

60 Jalan Lam Huat #03 - 35/36, Singapore (737869)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SGV1627L**  
 Vehicle Reg. Date: **6/6/2007**  
 Make / Model : **MAZDA5 SP**  
 Engine No. : **LF10275513**  
 Chassis No. : **JM6CR10F170105110**

PAGE 1

**Estimates on Parts**

| No | Qty  | PARTICULARS                        | CONDITION | AMOUNT      | S/N       | ADJUSTED AMOUNT |
|----|------|------------------------------------|-----------|-------------|-----------|-----------------|
| 1  | 1    | TAILGATE WINDSCREEN MLDG           | X SVC     | \$ 127.00   |           |                 |
| 2  | 1    | TAILGATE                           | X R       | \$ 3,197.30 |           |                 |
| 3  | 1    | TAILGATE INNER TRIM                | X SVC     | \$ 161.20   |           |                 |
| 4  | 1set | TAILGATE INNER TRIM CLIPS          | X SVC     | \$ 20.00    |           |                 |
| 5  | 1    | TAILGATE LOCK                      | X SVC     | \$ 356.80   |           |                 |
| 6  | 2    | TAILGATE DAMPER LH/RH              | X SVC     | \$ 373.20   |           |                 |
| 7  | 1    | TAILGATE EMBLEM "MAZDA 5"          | - NEC     | \$ 70.00    |           | \$ 70.00        |
| 8  | 1    | TAILGATE LOGO                      | - NEC     | \$ 71.90    |           | \$ 71.90        |
| 9  | 1    | TAIL LAMP LH                       | X SVC     | \$ 746.30   |           |                 |
| 10 | 1    | REAR BUMPER                        | - CR4     | \$ 944.30   |           | \$ 944.30       |
| 11 | 1    | REAR BUMPER RETAINER LH            | - BR      | \$ 32.50    |           | \$ 32.50        |
| 12 | 1set | REAR BUMPER CLIPS                  | - Nec     | \$ 30.00    |           | \$ 30.00        |
| 13 | 1    | REAR BUMPER SIDE GARNISH LH        | - Mis     | \$ 127.50   |           | \$ 127.50       |
| 14 | 1    | REAR BUMPER REFLECTOR LH           | - Mis     | \$ 53.00    |           | \$ 53.00        |
| 15 | 1    | REAR END PANEL OUTER               | - nb      | \$ 510.70   |           | \$ 510.70       |
| 16 | 1    | REAR END PANEL INNER               | X SVC     | -           |           |                 |
| 17 | 1    | REAR END TOP GARNISH               | X SVC     | \$ 122.10   |           |                 |
| 18 | 1set | REAR END TOP GARNISH CLIPS         | X SVC     | \$ 20.00    |           |                 |
| 19 | 1    | REAR FENDER LH                     | X R       | \$ 1,627.50 |           |                 |
| 20 | 1    | REAR FENDER LOWER INNER TRIM LH    | X SVC     | \$ 547.20   |           |                 |
| 21 | 1set | REAR FENDER LOWER INNER TRIM CLIPS | X SVC     | \$ 30.00    |           |                 |
| 22 | 1    | REAR FENDER MUDGUARD LH            | - Def     | \$ 35.50    |           | \$ 35.50        |
| 23 | 1    | REAR FENDER INNER SHIELD LH        | X SVC     | \$ 37.40    |           |                 |
| 24 | 1set | REAR FENDER INNER SHIELD CLIPS     | X SVC     | \$ 20.00    |           |                 |
| 25 | 1    | EXHAUST PIPE (End chrome pipe)     | - no      | \$ 1,194.30 |           | \$ 1,194.30     |
| 26 | 1    | EXHAUST MOUNTING                   | X SVC     | \$ 42.40    |           |                 |
| 27 | 1    | REAR END PANEL SEALANT             | X SVC     |             |           |                 |
| 28 | 1    | REAR FENDER SEALANT                | X SVC     |             |           |                 |
| 29 | 1    | SUNDRIES                           | X SVC     |             |           |                 |
| 30 | 1set | REVERSE SENSOR                     | - short   |             | \$ 200.00 |                 |
| 31 | 1    | REAR NUMBER PLATE                  | X SVC     |             |           |                 |
| 32 | 0    | 0                                  |           |             |           |                 |
| 33 | 0    | 0                                  |           |             |           |                 |
| 34 | 0    | 0                                  |           |             |           |                 |
| 35 | 0    | 0                                  |           |             |           |                 |
| 36 | 0    | 0                                  |           |             |           |                 |
| 37 | 0    | 0                                  |           |             |           |                 |
| 38 | 0    | 0                                  |           |             |           |                 |
| 39 | 0    | 0                                  |           |             |           |                 |
| 40 | 0    | 0                                  |           |             |           |                 |

\$ 200.00 \$ 3,069.70

410  
 150  
 1,924.7  
 - 20%  
 1,539.76

**Tel : 6358 3031 | Fax No : 6694 4929**

$P = 1,539.75$   
 $N = 200$   
 $L = 1,780$   


---

 $3,519.76$   
 $- 2096$   


---

 $2,815.81$   


---

$L/S$   
 $\$2,800$   
 4 days

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

60 Jalan Lam Huat #03 - 35/36, Singapore (737869)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SGV1627L**

Vehicle Reg. Date: **6/6/2007**

Make / Model : **MAZDA5 SP**

Engine No. : **LF10275513**

Chassis No. : **JM6CR10F170105110**

PAGE 1

Estimates on Parts

| No | Qty  | PARTICULARS                              | CONDITION | AMOUNT | S/N       | ADJUSTED AMOUNT |
|----|------|------------------------------------------|-----------|--------|-----------|-----------------|
| 1  | 1    | TAILGATE WINDSCREEN MLDG X SVC           |           |        |           |                 |
| 2  | 1    | TAILGATE X R                             |           |        |           |                 |
| 3  | 1    | TAILGATE INNER TRIM X SVC                |           |        |           |                 |
| 4  | 1set | TAILGATE INNER TRIM CLIPS X SVC          |           |        |           |                 |
| 5  | 1    | TAILGATE LOCK X SVC                      |           |        |           |                 |
| 6  | 2    | TAILGATE DAMPER LH/RH X SVC              |           |        |           |                 |
| 7  | 1    | TAILGATE EMBLEM "MAZDA 5" / NEC          |           |        |           |                 |
| 8  | 1    | TAILGATE LOGO / NEC                      |           |        |           |                 |
| 9  | 1    | TAIL LAMP LH X SVC                       |           |        |           |                 |
| 10 | 1    | REAR BUMPER / CRY                        |           |        |           |                 |
| 11 | 1    | REAR BUMPER RETAINER LH / BR             |           |        |           |                 |
| 12 | 1set | REAR BUMPER CLIPS / NEC                  |           |        |           |                 |
| 13 | 1    | REAR BUMPER SIDE GARNISH LH / MIF        |           |        |           |                 |
| 14 | 1    | REAR BUMPER REFLECTOR LH / MIF           |           |        |           |                 |
| 15 | 1    | REAR END PANEL OUTER ? / PP              |           |        |           |                 |
| 16 | 1    | REAR END PANEL INNER X SVC               |           |        |           |                 |
| 17 | 1    | REAR END TOP GARNISH X SVC               |           |        |           |                 |
| 18 | 1set | REAR END TOP GARNISH CLIPS X SVC         |           |        |           |                 |
| 19 | 1    | REAR FENDER LH X R                       |           |        |           |                 |
| 20 | 1    | REAR FENDER LOWER INNER TRIM LH X SVC    |           |        |           |                 |
| 21 | 1set | REAR FENDER LOWER INNER TRIM CLIPS X SVC |           |        |           |                 |
| 22 | 1    | REAR FENDER MUDGUARD LH X / DEF          |           |        |           |                 |
| 23 | 1    | REAR FENDER INNER SHIELD LH X SVC        |           |        |           |                 |
| 24 | 1set | REAR FENDER INNER SHIELD CLIPS X SVC     |           |        |           |                 |
| 25 | 1    | EXHAUST PIPE / PP                        |           |        |           |                 |
| 26 | 1    | EXHAUST MOUNTING X SVC                   |           |        |           |                 |
| 27 | 1    | REAR END PANEL SEALANT X SVC             |           |        | \$ 80.00  |                 |
| 28 | 1    | REAR FENDER SEALANT X SVC                |           |        | \$ 100.00 |                 |
| 29 | 1    | SUNDRIES X SVC                           |           |        | \$ 60.00  |                 |
| 30 | 1set | REVERSE SENSOR / Short                   |           |        | \$ 300.00 | 200             |
| 31 | 1    | REAR NUMBER PLATE X SVC                  |           |        | \$ 50.00  |                 |
| 32 | 0    | 0                                        |           |        |           |                 |
| 33 | 0    | 0                                        |           |        |           |                 |
| 34 | 0    | 0                                        |           |        |           |                 |
| 35 | 0    | 0                                        |           |        |           |                 |
| 36 | 0    | 0                                        |           |        |           |                 |
| 37 | 0    | 0                                        |           |        |           |                 |
| 38 | 0    | 0                                        |           |        |           |                 |
| 39 | 0    | 0                                        |           |        |           |                 |
| 40 | 0    | 0                                        |           |        |           |                 |

**Tel : 6358 3031 | Fax No : 6694 4929**

PAGE 1

[illegible]

Repair day - ~~2~~ 4 days

Sun Pin (Ude)

24/06/2020.

TP without prejudice.