

Trans-cab Auto Services Pte Ltd**AAD2006-060**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9797U

Vehicle No.:	SHB 9797U
Chassis No.:	AYH300090004
Vehicle Make:	TOYOTA
Vehicle Model:	ALPHARD
Date of Accident :	22.6.2020
Third Party Insurer :	AIG
Date of Registration :	17/12/2019

	PART		LIST
1	BUMPER COVER REAR	\$	2,078.20
2	BUMPER, REAR COVER	\$	290.30
3	REAR END PANEL	\$	781.70
4	TAILGATE	\$	2,040.50
5	SUPPORT, REAR BUMPER SIDE, RH	\$	240.00
6	SUPPORT, REAR BUMPER SIDE, LH	\$	240.00
7	LAMP ASSY, RR	\$	932.90
8	LOCK ASSY, BACK DOOR	\$	800.20
9	BOARD ASSY, BACK DOOR TRIM	\$	734.50

TOTAL	\$	8,138.30
25%	\$	2,034.58
	\$	6,103.73

	Special Nett		
1SET	PARKING AID	\$	4,000.00
2	PARKING AID, SENSOR ULTRASONIC	\$	785.60
2	PARKING AID, SENSOR ULTRASONIC	\$	785.60
1SET	REAR BUMPER CLIP	\$	80.00
1SET	REAR RH SIDE BUMPER SUPPORT CLIP	\$	35.00
1SET	REAR LH SIDE BUMPER SUPPORT CLIP	\$	35.00
1	PLATE, BACK DOOR - Alphard	\$	52.00
1	PLATE, BACK DOOR - E- FOUR	\$	41.00
1	EMBLEM SUB-ASSY	\$	72.40

Trans-cab Auto Services Pte Ltd**AAD2006-060**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9797U

1	PLATE, BACK DOOR- TOYOTA LOGO	\$	68.20
---	-------------------------------	----	-------

TOTAL	\$	5,954.80
--------------	-----------	-----------------

TOTAL PARTS	\$	12,058.53
--------------------	-----------	------------------

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	180.00
--	----	--------

To check steering geometry and computer wheel alignment	\$	220.00
---	----	--------

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00
---	----	--------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00
---	----	----------

Putty and spray painting of the affected portion.	\$	3,000.00
---	----	----------

To transfer of tire, rim and on wheel balancing.	\$	170.00
--	----	--------

To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	170.00
---	----	--------

To Rust-Proofing Of The Affected Areas.	\$	170.00
---	----	--------

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
--	----	--------

Trans-cab Auto Services Pte Ltd**AAD2006-060**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9797U

To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00
To Check Electrical Lighting Concerned.	\$	170.00
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00
To reinstall rear bumper parking sensor.	\$	170.00

TOTAL	\$	8,350.00
--------------	-----------	-----------------

Over All Total	\$	20,408.53
-----------------------	-----------	------------------

PART BY PART (REPAIR DAY)**10 DAYS**