Not Notherial Resury Bepaint

AAD2006-060

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

BOARD ASSY, REAR FLOOR, NO.1 /~ X

COJGST Reg. No. 201019626G

SHB 9797U

SHB 9797U Vehicle No.: 2 3 JUN 2020 AYH300090004 Chassis No.: TOYOTA Vehicle Make: **ALPHARD** Vehicle Model: 22.6.2020 Date of Accident : AIG Third Party Insurer: 17/12/2019 Date of Registration: PART s Bil cm 2,078.20 COVER, REAR BUMPER PLATE, REAR BUMPER, RH COVER, REAR BUMPER, UPPER RH 240.00 SUPPORT, REAR BUMPER SIDE, RH 240.00 X SUPPORT, REAR BUMPER SIDE, LH SUPPORT, REAR BUMPER SIDE NO.1, RH 1 SUPPORT, REAR BUMPER SIDE NO.1, LH 1 REFLECTOR ASSY, REFLEX, RH 1 Snx REFLECTOR ASSY, REFLEX, LH 1 PANEL SUB-ASSY, BODY LOWER BACK, OUTER HU 1 PANEL SUB-ASSY, BODY LOWER BACK, INNER 12 & 1 RX PAN, REAR FLOOR 1 RX REINFORCEMENT, REAR FLOOR PANEL 1 PLATE, BACK DOOR SCUFF 1 PANEL SUB-ASSY, BACK DOOR \$ 2,040.50 -1 Dil IDd -WEATHERSTRIP, BACK DOOR 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE JWX 1 CUSHION, BACK DOOR PANEL LX 1 LAMP SUB-ASSY, LICENCE PLATE Jax 1 1 LOCK ASSY, BACK DOOR Smx STAY ASSY, BACK DOOR, LH 1 Jux STAY ASSY, BACK DOOR, RH 1 BOARD ASSY, BACK DOOR TRIM Nd Sm 1 BOX, DECK FLOOR, REAR 1 BOARD ASSY, REAR FLOOR, NO.2 5 x

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330 CO./GST Reg. No. 201019626G

SHB 9797U

- 1 LAMP ASSY, REAR, RH
 1 LAMP ASSY, REAR, LH

 In x
- 1 LENS AND BODY, REAR COMBINATION LAMP, LH
- 1 LENS AND BODY, REAR COMBINATION LAMP, RH Su x
- 1 GARNISH, BACK DOOR OUTSIDE, LOWER RH
- 1 EXTENSION, REAR WHEEL OPENING, RH 7. X
- 1 PANEL, QUARTER, RH
- n x
- 1 LINER, REAR WHEEL HOUSE, RH 1 X

	TOTAL	\$	4,598.70	
	25%	\$	1,149.68	
		\$	3,449.03	
	and the first of the second of			
	Special Nett		e.	
1SET	PARKING AID	\$	1,200.00 X	
1SET	REAR BUMPER CLIP	\$	Mr 90.00 -	55
1SET	REAR LH SIDE BUMPER SUPPORT CLIP	\$	na 60.00)	
1SET	REAR RH SIDE BUMPER SUPPORT CLIP	\$	~ 60.00	
1SET	REAR LH SIDE BUMPER SUPPORT NO.1 CLIP	\$	N~ 60.00	
1SET	REAR RH SIDE BUMPER SUPPORT NO.1 CLIP	\$	ルへ 60.00 > X	
1SET	BACK DOOR OUTSIDE GARNISH CLIP	\$	Nr 45.00)	
1	BACK DOOR PANEL TOYOTA LOGO	\$	Ne, 68.20	Š.
1	BACK DOOR PANEL WORDING "Alphard"	\$	1 52.00 U	
1	BACK DOOR PANEL WORDING "E-Four"	\$	12c 41.00 -	
1	BACK DOOR PANEL WORDING "Hybrid Synergy Drive"	\$	Ma 72.40	
1SET	REAR LAMP CLIP	\$	15.00 X	
1SET	REAR END PANEL INNER TRIM CLIP	\$	Mz 40.00 -	-
2	REAR WINDSCREEN SEALANT	\$	MC 150.00 401	nı_
1	WINDSCREEN MOULDING	\$	Ma 200.00 L	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	Ma 130.00 3051	
1	Rear Bumper Protector	\$	Nec 180.00 3052	_
1SET	REAR COMBINATION LAMP CLIP	\$	~~ 45.00 x	
1SET	REAR NUMBER PLATE WITH HOLDER	\$	Sm 200.00 K	
2	END PANEL SEAM SEALANT	\$	1 200.00 X	
Q1-55-1	TABLE DANGE CONTROL OF THE PROPERTY OF THE PRO	7.0		

Trans-cab Auto Services Pte Ltd			AAD2006-060
No. 2 A	ng Mo Kio Street 63 Singapore 569111		
Tel No.	: 6287 6666 Fax No. : 6257 1330		
CO./GS	T Reg. No. 201019626G		
SHB 97	797U		
			444
1SET	REAR FENDER LINER CLIP	\$	NA 50.00 X
1SET	BACK DOOR TRIM BOARD CLIP	\$	255.00 X
1SET	REAR DECK FLOOR BOX CLIP	\$	<i>√</i> ~ 40.00 ¹
	TOTAL	\$	3,143.60
	TOTAL PARTS	\$	6,592.63
	de traje el la la Article de la la la Article de la		
	LABOUR The Negersan's		
	Panel Beating, Knocking And Straightening The Necessary		
	Portion, Remove And Renewal Of Parts, Adjust And Realign	¢	6,500.00 Fool
	The Same	\$	0,500.00
	To transfer of bootlid fittings, attachments and perform		
	water seepage test.	\$	180.00 601
	To check steering geometry and computer wheel alignment	\$	NN 220.00 X
	To remove and refit interior fittings, trimings, garnish,		٥.
	fittings and other, to enable repair.	\$	380.00
	Labour charge to mount and dismount vehicle on jig bench,		
	to facilitate repair.	\$	NA 380.00 X
	To transfer of rear bumper fittings, attachment and perform		
	water seepage test.	\$	~~ 170.00 X
	T. D. A. D. S. Franco Of The Affected Areas	\$	170.00 601
	To Rust-Proofing Of The Affected Areas.	J.	170.00 807
	To transfer of rear end panel fittings, attachment and		
	perform water seepage test.	\$	~~ 380.00 ×
	To transfer of rear luggage floor panel fittings, attachment		
	and perform water seepage test.	\$	NN 380.00 X

Trans-cab Auto Services Pte Ltd

AAD2006-060

No. 2 Ang Mo Kio Street 63 Singapore 569111 Fax No.: 6257 1330 Tel No.: 6287 6666

CO./GST Reg. No. 201019626G

SHB 9797U

PART BY PART (REPAIR DAY)	-	25 DAYS	
Over All Total	\$	23,082.63	= 14
TOTAL	\$	16,490.00	
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	12
o reinstall rear bumper parking sensor.	\$	170.00	60
Putty and spray painting of the affected portion.	\$	6,500.00	
o transfer of tire, rim and on wheel balancing.	\$	170.00	X
To supply and re-do rear end panel insulation padding.	\$	380.00	X
o transfer of rear fender fittings, attachment and perform vater seepage test.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: