

Not Authorized
Returning BY paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9797U

AAD2006-060

87369.83

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHB 9797U

AYH300090004

TOYOTA

ALPHARD

22.6.2020

AIG

17/12/2019

	PART	
1	BUMPER COVER REAR	1780.57
2	BUMPER, REAR COVER	
3	REAR END PANEL	
4	TAILGATE	1956.20
5	SUPPORT, REAR BUMPER SIDE, RH	
6	SUPPORT, REAR BUMPER SIDE, LH	
7	LAMP ASSY, RR	
8	LOCK ASSY, BACK DOOR	742.00
9	BOARD ASSY, BACK DOOR TRIM	

	LIST	
\$	Bp	2,078.20 ✓
\$	Sn	290.30 X
\$	Bp	781.70 ✓
\$	Bp	2,040.50 ✓
\$	Sn	240.00 X
\$	Sn	240.00 X
\$	Sn	932.90 X
\$	nd	800.20 ✓
\$	nd	734.50 ✓

TOTAL	\$	8,138.30
25%	\$	2,034.58
	\$	6,103.73

Special Nett

1SET	PARKING AID
2	PARKING AID, SENSOR ULTRASONIC
2	PARKING AID, SENSOR ULTRASONIC
1SET	REAR BUMPER CLIP
1SET	REAR RH SIDE BUMPER SUPPORT CLIP
1SET	REAR LH SIDE BUMPER SUPPORT CLIP
1	PLATE, BACK DOOR - Alphard
1	PLATE, BACK DOOR - E- FOUR
1	EMBLEM SUB-ASSY

\$	nd/shom	4,000.00	Boosn
\$	Sn	785.60	X
\$	Sn	785.60	X
\$	nn	80.00	✓
\$	nn	35.00	X
\$	nn	35.00	X
\$	nn	52.00	✓
\$	nn	41.00	✓
\$	nn	72.40	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9797U**AAD2006-060**

1 PLATE, BACK DOOR- TOYOTA LOGO

\$ *me* 68.20 ✓**TOTAL \$ 5,954.80****TOTAL PARTS \$ 12,058.53****LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ 180.00 *bol*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *bol*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 3,000.00 *Food*

Putty and spray painting of the affected portion.

\$ 3,000.00 *bol*

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To transfer of rear bumper fittings, attachment and perform water seepage test.

\$ *nn* 170.00 X

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *bol*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9797U**AAD2006-060**

To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	120/
To Check Electrical Lighting Concerned.	\$	170.00	20/
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00	X
To reinstall rear bumper parking sensor.	\$	170.00	60/

TOTAL	\$	8,350.00
--------------	-----------	-----------------

Over All Total	\$	20,408.53
-----------------------	-----------	------------------

PART BY PART (REPAIR DAY)~~10 DAYS~~
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: