



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 4259P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	694.50	-
8	FRONT BUMPER CLIP @\$6.50 (CONSISTENT)	NECESSARY	52.00	30.00
1	FRONT L/H BUMPER SIDE RETAINER (CONSISTENT)	NOT NECESSARY	26.30	-
1	FRONT L/H HEADLAMP (CONSISTENT)	CRACKED	2,568.00	2,380.00
1	FRONT L/H FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	380.00	-
1	FRONT L/H FENDER COWLING (CONSISTENT)	NOT NECESSARY	125.00	-
8	FRONT L/H FENDER COWLING CLIP @\$6.50 (CONSISTENT)	NOT NECESSARY	52.00	-
1	FRONT L/H DOOR SIDE MIRROR ASSY (CONSISTENT)	DAMAGED	980.00	980.00
1	FRONT L/H DOOR SIDE MIRROR COVER (CONSISTENT)	MISSING	130.00	130.00
1	FRONT L/H TYRE (CONSISTENT)	NOT NECESSARY	350.00	-
1	FRONT L/H HEADLAMP LOWER BRACKET (CONSISTENT)	CRACKED	62.10	62.10
1	FRONT L/H DOOR SIDE MIRROR LAMP (CONSISTENT)	CUT	68.90	68.90
	LESS 20% DISCOUNT		-	-730.20
			5,488.80	2,920.80
<u>SPECIAL NETT ITEMS</u>				
1	FRONT L/H RIM (CONSISTENT)(SN)	CUT	800.00	550.00
			800.00	550.00
<u>LABOUR</u>				
	TO CHECK WHEEL ALIGNMENT.		150.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	50.00
	TOWING FEE.	NOT NECESSARY	150.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT L/H FENDER.		800.00	500.00
	SPRAY PAINTING.		600.00	550.00
			1,950.00	1,210.00
GRAND TOTAL			8,238.80	4,680.80



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00
---	--	--	----------

Report Ref No. CC4/ASM20006594/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.