

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM20006594/Apa3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Date: 14-09-2020 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 7171Z	Veh. Inspected	SLL 4259P
	Policy No.	GA510793	Coverage (\$)	0.00
	Claim No.	S0M02L2C	Excess (\$)	0.00
	Assign From		Assign Date	23/06/2020
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU FORESTER	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JF1SJGK85GG081462	Colour	SILVER
	Odometer	62042	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	06/04/2020	Inspection Date	24/06/2020
	Survey held at	SM AUTOMOTIVE		
	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			