

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

23/06/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

JF1SJGK85GG081462

TPAXA

Xiao Tong

Accident date: 06-04-2020

Estimated repair cost for vehicle no: SLL4259P SUBARU FORESTER 2.0 A 17'

CHASSIS: JF1SJGK85GG081462

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front Bumper <i>Regis</i>		\$694.50 <i>x</i>
2	8	Front Bumper Clip <i>Neu</i>	\$6.50	\$52.00 <i>x 30</i>
3	1	Front L/H Bumper Side Retainer <i>Abc neu</i>		\$26.30 <i>x</i>
4	1	Front L/H Headlamp <i>Coached</i>		\$2,568.00 <i>2380</i>
5	1	Front L/H Fender <i>Regis</i>		\$380.00 <i>x</i>
6	1	Front L/h Fender Cowling <i>Regis</i>		\$125.00 <i>x</i>
7	8	Front L/H Fender Cowling Clip <i>Regis</i>	\$6.50	\$52.00 <i>x</i>
8	1	Front L/H Door Side Mirror Assy <i>Damaged</i>		\$980.00 <i>x</i>
9	1	Front L/H Door Side Mirror Cover <i>Missing</i>		\$130.00 <i>x</i>
10	1	Front L/H Rim <i>Regis</i>		\$800.00 <i>550/50</i>
11	1	Front L/H Tyre <i>Regis</i>		\$350.00 <i>x</i>
12	1	Front L/H Headlamp Lower Bracket <i>Coached 62.10</i>		
13	1	Front L/H Door Side Mirror Lamp <i>Regis 68.90</i>		
			Subtotal:-	\$6,157.80

3651

S-N 550

2920.80

Labour charges

To check wheel alignment

~~\$150.00~~ 80

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 50

Towing fee

~~\$150.00~~ X

Panel beating

~~\$800.00~~ 500

Spray painting

~~\$600.00~~ 550

Subtotal:- \$1,950.00

Total:- \$8,107.80

total: 4680 80

4/s: 3.7k

0.4 days

3.7k

- LKK Auto Consultants** hence notify
the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: