

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMF893D

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 14/06/2020
TP Veh Reg No: SCU1546P

Estimate No: ES2090493/YISHUN
Date: 02 Jul 2020
Policy No: 5104945623-01
Veh Reg No: SMF893D
Make/Model: TOYOTA TOYOTA VIOS
1.5 E (AUTO)
Chassis No: MR2B23F3501153269
Engine No: 2NR5285766
Reg. Date: 26/10/2018

Not Authorized
Resurvey B4 paint
3 days

Estimate Repair Cost to Vehicle No :SMF893D

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT BUMPER	423.10	1 PC	423.10	✓
2 FRONT BUMPER RH FOG LAMP GARNISH	103.70	1 PC	103.70	✓
3 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	✓
			547.80	
		Less 25%	136.95	410.85
Labour				
4 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,FOG LAMPS,CENTRE LOWER GRILLE,KNOCK & REPAIR FRT RH FENDER & REALIGN THE SAME	500.00	1 LA	500.00	350
5 PUTTY & RESPRAY ON FRT RH FENDER,FRT BUMPER	500.00	1 LA	500.00	400
			1,000.00	1,000.00
			Total	S\$ 1,410.85
			Add GST @ 7%	98.76
			Total Amount Payable	S\$ 1,509.61

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance

Acknowledged by Repairer
Signature:

AUTHORISED SIGNATURE