

Vehicle No: SMD 7645 T
 Model: Maserati Camiocorsa
 Chassis No:
 Year of manufacturing:

DOA: 20.06.2020

S/No	Qty	Items	Unit Price	Amount
1	1	Rear Bumper / <i>cc</i>		\$ 4650.25 -
2	2	Rear Bumper Bracket X <i>nn</i>		\$ 98.34 -
3	1	Rear Bumper Top Garnish / <i>BR</i>		\$ 285.50 -
4	1	Rear Reinforcement X <i>nn</i>		\$ 1285.00 -
5	1	Rear Boot / <i>CCA</i> C New and old. After repair photos		\$ 6750.15 - 6202.68
6	1	Rear Boot Weatherstrip / <i>Tw</i>		\$ 175.85 -
7	1	LHS Rear Boot Inner Taillamp X <i>nn</i>		\$ 450.00 -
8	1	RHS Rear Boot Inner Taillamp X <i>nn</i>		\$ 450.00 -
9	1	Rear Boot Logo / <i>nc</i>		\$ 93.20 -
10	1	End Panel X <i>repair</i>		\$ 1035.00 -
11	1	End Panel Top Garnish X <i>nn</i>		\$ - -
12	1	RHS Eshuast Muffler / <i>BT</i> (After repair photo) New and old.		\$ 4050.00 - 3000
				14407.48
				\$ -
				10% \$ -
Total for spare parts				\$ -
				12966.73

Special Nett		Items			
1	10	Rear Bumper Clip / <i>nc</i>	\$ 25.00	\$ 250.00	20
2	1	Rear Reverse Sensor / <i>DM</i>	\$ 350.00	\$ 350.00	200
3	1	Rear Boot Spoiler X <i>nn</i>	\$ 2,500.00	\$ 2,500.00	
4	1	Rear Boot Sticker / <i>nc</i>	\$ 150.00	\$ 150.00	
5	1	Rear No. Plate / <i>nc</i>	\$ 35.00	\$ 35.00	15

Total for SP \$ 3,285.00
 Sub-Total for Parts :

14671.73
 -20%: 11700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary terms must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

S/No	Qty	Items	Unit Price	Amount	
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-	\$	1,200.00	600.
2		To putty and spray paint on all accident damage parts and other accident	\$	1,000.00	800
3		To check wiring system to facilitate repair and refit the same	\$	80.00	70 30
4		Apply rust proofing on the adjacent panels	\$	50.00	X NN
5		Reset engine management system with diagnostic fault	\$	80.00	X NN
6		To supply under coating / putty on parts replaced	\$	60.00	X NN
8		To perform water seepage test after repair	\$	150.00	X NN
9		To remove & refit rear bumper sensor	\$	60.00	40
10		To remove and replace windscreen	\$	100.00	X NN
				1470	
TOTAL AMOUNT :				\$ 2,780.00	
OVERALL COST:					

5 Days.

Lumpsum Repair.

After repair photos.

23/6/2020.

Gino Qiang - 82880282.