

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

Vehicle No: SMD 7645 T
Model: Maserati Camiocorsa
Chassis No:
DOA: 20.06.2020
Year of manufacturing:

S/No	Qty	Items	Unit Price	Amount
1	1	Rear Bumper <i>BR</i>		\$ 1650.00 <i>✓</i>
2	2	Rear Bumper Bracket <i>X NN</i>		\$ 98.34 <i>-</i>
3	1	Rear Bumper Top Garnish <i>BR</i>		\$ 285.00 <i>✓</i>
4	1	Rear Reinforcement <i>X NN</i>		\$ 1280.00 <i>-</i>
5	1	Rear Boot <i>CRA C New and old. After repair photos</i>		\$ 6750.15 <i>6000.68</i>
6	1	Rear Boot Weatherstrip <i>Twil</i>		\$ 175.00 <i>✓</i>
7	1	LHS Rear Boot Inner Taillamp <i>X NN</i>		\$ 450.00 <i>-</i>
8	1	RHS Rear Boot Inner Taillamp <i>X NN</i>		\$ 450.00 <i>-</i>
9	1	Rear Boot Logo <i>MC</i>		\$ 92.00 <i>✓</i>
10	1	End Panel <i>X repair</i>		\$ 1035.00 <i>-</i>
11	1	End Panel Top Garnish <i>X NN</i>		\$ - <i>-</i>
12	1	RHS Exhaust Muffler <i>BT (After repair photo) New and old.</i>		\$ 4050.00 <i>3000.00</i>
				\$ -
10%				\$ -
Total for spare parts				\$ -

Special Nett

1	10	Rear Bumper Clip <i>MC</i>	\$ 25.00	\$ 250.00 <i>20.00</i>
2	1	Rear Reverse Sensor <i>DM</i>	\$ 350.00	\$ 350.00 <i>200.00</i>
3	1	Rear Boot Spoiler <i>X NN</i>	\$ 2,500.00	\$ 2,500.00
4	1	Rear Boot Sticker <i>MC</i>	\$ 150.00	\$ 150.00 <i>✓</i>
5	1	Rear No. Plate <i>MC</i>	\$ 35.00	\$ 35.00 <i>15.00</i>
Total for SP			\$	3,285.00
Sub-Total for Parts :				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary (items) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

511861.75
 52420.00
 514291.75
 100
 512862.57
 705
 513647.57
 1470.00
 515117.57
 512094.05

12050.00

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-	\$	1,200.00
2		To putty and spray paint on all accident damage parts and other accident	\$	1,000.00
3		To check wiring system to facilitate repair and refit the same	\$	80.00
4		Apply rust proofing on the adjacent panels	\$	50.00
5		Reset engine management system with diagnostic fault	\$	80.00
6		To supply under coating / putty on parts replaced	\$	60.00
8		To perform water seepage test after repair	\$	150.00
9		To remove & refit rear bumper sensor	\$	60.00
10		To remove and replace windscreen	\$	100.00

TOTAL AMOUNT : \$ 2,780.00
OVERALL COST:

5 Days.

Lumpsum repair.

After repair photos.

23/6/2020.

Gmo Qian - 8288028 2.

LP = \$16004.95
- 10%
\$14404.45
SW d \$60
\$14964.45
LE \$1470.00
\$16434.45
- 20%
\$13147.56

\$11689.55