

NEW ZEN WERKZ PTE LTD

BLOCK 3 KAKI BUKIT ROAD 1 #03-04 EUNOS TECHNOLINK

SINGAPORE 415935

Tel : (65) 67428117 HP: 92712214 Fax: (65) 67428117

TP 1st Cap

22nd JUNE 2020

Blk 3 Kaki Bukit Road 1
03 - 04 Eunoss Technolink
Singapore 415935

Khaichan

JTHBK262502 086724

Accident date: 26th JAN 2020

Estimated repair costs for vehicle no: SMH250Z TOYOTA LEXUS IS 2020

S/n	Qty	Items/nett	U/price	Amount	
				\$1,585.00	883
1	1	Front bumper <i>detached</i>	\$188.00	\$376.00	x
2	2	Front bumper retainer <i>new</i>	\$12.10	\$96.80	30
3	8	Front Bumper clips <i>new</i>		\$185.20	x
4	1	Front Bumper inner sponge <i>new</i>		\$1,125.00	✓
5	1	Front head lamp -RH <i>cracked</i>		\$124.10	✓
6	1	Front head lamp lower bracket <i>cracked</i>		\$245.00	x
7	1	fog lamp -RH <i>cracked</i>			
Subtotal :-				<u>\$3,737.10</u>	

2162.10
1945 89

Labour charges

Panel beating

Spray painting charges

500 ~~\$300.00~~ 250

~~\$300.00~~ 250

\$600.00

Total:-

\$4,337.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 2445 89 Admin Lj
H/S: 1.9/K. H/S 23/06/20
03 Days.