

YSK Auto Workshop

No. 1 Kaki Bukit Avenue 6, #01-49 (Autobay), Singapore 417883

H/P: 9640 2541

Email: dannyskyeo@gmail.com

Vehicle number: SMM2883H

Vehicle Make & Model: HONDA VEZEL

Qty	List Items	Amount \$
1	Tailgate <i>Dented</i>	1,209.10 1100
1	Tailgate outer garnish <i>for new</i>	341.20 x
1	Tailgate emblem 'H'	32.20 x
1	Tailgate emblem "VEZEL" <i>new</i>	45.90 ✓
2	Tailgate lamps - L/R @ 311.80 <i>1st</i>	623.60 ✓
1 set	Tailgate glass moulding <i>new</i>	112.20 ✓
1	Tailgate inner lock <i>Damaged</i>	204.10 ✓
1	Tailgate inner trim <i>cracked</i>	310.60 ✓
1	Tailgate inner pull pocket <i>for new</i>	86.60 x
1	Tailgate lock striker	28.60 x
1	Tailgate w/strip <i>1st</i>	114.10 ✓
2	Tailgate dampers - L/R @ 108.50 <i>new</i>	217.00 x
2	Tailgate hinges @ 74.10 <i>new</i>	148.20 x
2	Tailgate stoppers @ 12.20 <i>new</i>	24.40 x
2	Taillamps - L/R @ 381.90 <i>cracked</i>	763.80 ✓
1	Rear bumper <i>distorted</i>	761.60 ✓
2	Rear bumper reflectors - L/R @ 89.60 <i>cracked</i>	179.20 ✓
2	Rear bumper sides - L/R @ 241.60 <i>behind</i>	483.20 380
2	Rear bumper side retainers - L/R @ 48.60 <i>new</i>	97.20 48
10	Rear bumper clips @ 4.50 <i>new</i>	45.00 30
1	Rear end panel <i>Dented</i>	560.90 ✓
1	Rear end panel inner trim <i>behind</i>	182.90 ✓
1	Rear exhaust silencer <i>for new</i>	688.10 x
1	Rear exhaust insulator	70.80 x
2	Rear exhaust mountings @ 18.60 <i>new</i>	37.20 x
1	Rear floor board <i>for new</i>	380.60 x
1	Rear floor tray	391.20 x
1	Rear floor panel <i>new</i>	911.40 x
1	Rear floor panel undercover new NN	241.20 x
2	Rear fender inner trims - L/R @ 290.80 <i>new</i>	581.60 x
1	Rear smart keyless antenna <i>new</i>	180.90 x

Vehicle number: SMM2883H

Vehicle Made & Model: HONDA VEZEL

1	Rear smart keyless buzzer	192.90	84
2	Rear fender wheel arch garnishes - L/R @ 241.20	482.40	
Sub-total		10,729.90	
Less 20%		2,145.98	
Total List		8,583.92	

5310.90
4408.72

Special Nett Items

1 set	Rear reverse sensor	280.00	200
1	Rear reverse camera	450.00	
1 set	Tailgate glass sealant	80.00	60
1 set	Tailgate glass foam tape	65.00	40
Total Special Nett		875.00	

300

Labour charges

To check rear electrical wiring	50.00	30
To remove, refix tailgate glass	180.00	120
To remove, refix rear reverse camera / sensor	80.00	✓
To remove, refix rear exhaust systems	100.00	✓
To respray undercoating	120.00	80
To remove, refix rear interior trims to assist repair	120.00	80
Reinstall tailgate electrical & mechanical to new tailgate	180.00	80
To respray painting and etc	1,400.00	800
Panel beating, cut, weld remove & replacing above parts	1,500.00	900
Total Labour	3,730.00	

2170

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 13,188.92

total 6878.72
4/5 5.8k
06 Days.