

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC4/AIG20006604/KRS3Q2  
**Date:** 11/05/2021

**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 0999993850   |
| <b>Claimant Vehicle No :</b> | GBD4770P                             | <b>Insured Vehicle No :</b> | GZ7483Z      |
| Date of Loss:                | 22/06/2020                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 8768255620SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                                 |             |                   |
|-----------------------------|-------------------------------------------------|-------------|-------------------|
| Reg No:                     | <b>GBD4770P</b>                                 |             |                   |
| Make & Model:               | NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A) | Engine No:  | ZD30342688K       |
| Reg. Date:                  | 29/10/2014 (Man. Year: 2014)                    | Chassis No: | JN1SC2F24Z0856618 |
| Colour:                     | Silver                                          | Odometer:   | 144700 km         |
| Engine Capacity:            | 2953 cc                                         |             |                   |
| Market Value/New Car Price: | N/A                                             |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>               |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |             |                  |               |
|-------------------|-------------|------------------|---------------|
| Front Tyre Size:  | 195 R15X8   | Rear Tyre Size:  | 155 R12X8 (D) |
| Front Left Side:  | Condor 6 mm | Rear Left Side:  | Condor 4/4 mm |
| Front Right Side: | Condor 6 mm | Rear Right Side: | Condor 4/4 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 2,712.05          | 2,599.05          | 113.00            | 4.17          |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 1,600.00          | 1,200.00          | 400.00            | 25.00         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>4,312.05</b>   | <b>3,799.05</b>   | <b>513.00</b>     | <b>11.90</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>3,000.00</b>   |                   |               |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| (S\$)                                           | 4,312.05        | 3,000.00        | 1,312.05        | 30.43        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 301.84          | 210.00          | 91.84           | 30.43        |
| <b>Nett Amount (S\$)</b>                        | <b>4,613.89</b> | <b>3,210.00</b> | <b>1,403.89</b> | <b>30.43</b> |
| <b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b> |                 | 300.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 8.00            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>3,518.00</b> |                 |              |

INSPECTION

Date of Assignment: 24/06/2020

Date Inspected: 27/06/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)  
 Blk 1019 #01-374/382, Yishun Industrial Park A  
 Singapore 768761

**Adjuster:** KENNETH KONG**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition           | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------|---------------------|-------------|--------------|
| 1   | 1   |          | *REAR TAILGATE                  | Bent                | 1,459.60 FN | *1,459.60 FN |
| 2   | 1   |          | *REAR TAILGATE STICKER NISSAN   | Necessary           | 169.00 FN   | *169.00 FN   |
| 3   | 1   |          | *REAR TAILGATE LH HINGE         | Bent                | 182.90 FN   | *182.90 FN   |
| 4   | 1   |          | *REAR TAILGATE LH SAFETY LOCK   | Bent                | 36.00 FN    | *36.00 FN    |
| 5   | 1   |          | *LH TAILLAMP                    | Cracked             | 203.50 FN   | *203.50 FN   |
| 6   | 1   |          | *RH TAILLAMP                    | Cracked             | 203.50 FN   | *203.50 FN   |
| 7   | 1   |          | *RH TAILLAMP PANEL              | Repair              | 120.00 FN   | *- FN        |
| 8   | 1   |          | *70KM/H STICKER                 | Necessary           | 10.00 FS    | *10.00 FS    |
| 9   | 1   |          | *13 PAX STICKER                 | Necessary           | 10.00 FS    | *10.00 FS    |
| 10  | 1   |          | *SET REVERSE SENSOR             | Scratched / Shorted | 200.00 FS   | *200.00 FS   |
| 11  | 1   |          | *LH STOPPER                     | Cracked             | 15.00 FS    | *15.00 FS    |
| 12  | 1   |          | *TAILGATE INNER PROTECTOR       | Buckled             | 280.00 FS   | *280.00 FS   |
| 13  | 1   |          | *TAILGATE INNER PROTECTOR CLIPS | Necessary           | 30.00 FS    | *30.00 FS    |
| 14  | 1   |          | *REAR NUMBER PLATE              | Bent                | 30.00 FS    | *25.00 FS    |

F=Franchise part. S=SpcNett. N=NettItemDisc.

|                                                           |                 |                 |
|-----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                                    | <b>2,949.50</b> | <b>2,824.50</b> |
| <b>- Nett Item Discount on N Items 10.00/10.00% (S\$)</b> | 237.45          | 225.45          |
| <b>Total Parts (S\$)</b>                                  | <b>2,712.05</b> | <b>2,599.05</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                                                                                                      | Lab.Type | Repairer's      | Amount          |
|--------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                                                                                                                                                  |          |                 |                 |
| 1                              | REMOVE AND REFIT TAILLAMPS ,TAILGATE ASSY TO KNOCK AND REPAIR REAR END PANEL ,REAR CHASSIS ,FLOORBOARD PANEL,LH CORNER PILLAR ,LH SIDE GATE AND LOWER PANEL AND REALIGN THE SAME | New      | 800.00          | 600.00          |
| 2                              | PUTTY AND RESPRAY TAILGATE ,REAR END PANEL,LH SIDE GATE & LOWER PANEL ,REAR LH CORNER PILLAR AND REAR LH CHASSIS                                                                 | New      | 800.00          | 600.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                                                                                  |          | <b>1,600.00</b> | <b>1,200.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >