



**National Assessment Centre Services**  
 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933  
 TEL: 6841 0055 FAX: 6841 6315  
 Reg. No: 52983356E GST Reg. No. 20-0405911-H



**TAX INVOICE**

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. NA2003441  
 73 BRAS BASAH ROAD  
 #05-01 NTUC TRADE UNION HOUSE INV Date 01/07/2020  
 SINGAPORE 189556 Reference NS/INC20006606/T1qf3n2  
 Code INC4



**PROFESSIONAL SERVICE FEE**

Vehicle No. SHC 8622S  
 Insured Veh. SJY 3100A  
 Claim No. MT/1095010-002  
 Policy No. 5106125343  
 Accident Date 21/06/2020  
 Inspection Date 23/06/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>160.00</b>
<b>GST (7%)</b>	<b>11.20</b>
<b>Grand Total</b>	<b>171.20</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'National Assessment Centre Services'**

**National Assessment Centre Services**





# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20006606/T1qf3n2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 01-07-2020
Code: INC4	



### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SJY 3100A	<b>Veh. Inspected</b>	SHC 8622S
<b>Policy No.</b>	5106125343	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1095010-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	23/06/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HYUNDAI I40	<b>c.c</b>	1685
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	KMHLB41UMGU085744	<b>Colour</b>	BLUE
<b>Odometer</b>	520145	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/60 R16	HANKOOK	6 mm
<b>L/H Front Tyre</b>	205/60 R16	HANKOOK	6 mm
<b>R/H Rear Tyre</b>	205/60 R16	HANKOOK	6 mm
<b>L/H Rear Tyre</b>	205/60 R16	HANKOOK	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	21/06/2020	<b>Inspection Date</b>	23/06/2020
<b>Survey held at</b>	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8622S**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRT BUMPER	TO REPAIR SEE LABOUR	1,052.20	-
1	FRT FENDER LH	BENT	663.00	663.00
1	WING MIRROR LH	TO REPAIR SEE LABOUR	670.00	-
	LESS 20% DISCOUNT		-477.04	-132.60
			1,908.16	530.40
<b><u>NETT ITEMS</u></b>				
1	FRT DOOR COMFORTDELGRO LH (N)	CUT	75.00	75.00
	LESS 10% DISCOUNT		-7.50	-7.50
			67.50	67.50
<b><u>LABOUR</u></b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT BUMPER AND WING MIRROR LH.		600.00	420.00
	SPRAYPAINT CHARGE.		800.00	600.00
	CHECK ALL LIGHTING.		40.00	30.00
	TUFF COAT ON AFFECTED PARTS.		40.00	30.00
			1,480.00	1,080.00
<b>GRAND TOTAL</b>			<b>3,455.66</b>	<b>1,677.90</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,350.00</b>

Report Ref No. NS/INC20006606/T1qf3n2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHC 8622S

INSPECTION






## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHC 8622S

RE-INSPECTION

