

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 307E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER-RR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	PANEL ASSY-REAR DOOR LH	BENT	1,789.90	1,789.90
1	MOULDING ASSY-W/LINE RR D	TO REPAIR SEE LABOUR	110.10	-
1	CAP ASSY-WHEEL HUB	CUT	346.40	346.40
	LESS 20% DISCOUNT		-541.16	-427.26
			2,164.64	1,709.04
	NETT ITEMS			
1	APP LOGO REAR DOOR L/R CC (N)	NECESSARY	80.00	80.00
1	PATROL ONLY-STICKER (N)	NECESSARY	20.00	20.00
	LESS 10% DISCOUNT		-10.00	-10.00
			90.00	90.00
	SPECIAL NETT ITEMS			
1	PROTECTOR MAT (SN)	NOT NECESSARY	50.00	-
1	ADVERTISMENT STICKER - DOOR (SN)	NECESSARY	100.00	100.00
1	ADVERTISMENT STICKER - FENDER (SN)	NECESSARY	200.00	200.00
			350.00	300.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF COVER -RR BUMPER AND MOULDING ASSY-W/LINE RR D.		800.00	640.00
	SPRAYPAINT CHARGE.		800.00	600.00
	TRANSFER DOOR PARTS.		120.00	60.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
			-	-
			-	-
			1,800.00	1,330.00
	GRAND TOTAL		4,404.64	3,429.04

RECOMMENDED COST OF REPAIRS (CONFIRMED)			3,429.04
---	--	--	----------





Report Ref No. NS/INC20006608/T1yf3e2

MOHAMAD TAUFIKH

fouring.

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser