

PORT TRANSPORTATION PTE LTD

PAIR ESTIMATE

Vehicle No. : SH7177K 22.06.20

Date: 22.06.20

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G3)

MVA: LKE

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER		367.52	dec ✓ \$459.40
10	REAR BUMPER CLIPS		176	nu ✓ \$22.00 220
1	REAR BUMPER CENTRE MOULDING ASSY		361	nu ✓ \$451.25
1	REAR BUMPER MOULDING LOWER			AP \$155.00
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div>				
SUB TOTAL				\$1,087.65
LESS 20%				\$217.53
DISCOUNTED TOTAL				\$870.12
1	REAR NUMBER PLATE		10% 55	Tana ✓ \$25.00 Nett
1	REAR NUMBER PLATE TRIM COVER		49.5	de ✓ \$30.00 Nett
1	REAR BUMPER REVERSE SENSOR		10% - 162	nu ✓ \$180.00 Nett
904.52				
211.50				
580				
Labour Charge				
PANEL BEATING				320 \$350.00
SPRAY PAINTING CHARGE				200 \$250.00
WIRING CHARGE				30 \$50.00
REMOVE/REFIX REVERSE SENSOR				30 \$80.00
TOTAL LABOUR				\$730.00
ESTIMATE TOTAL				\$1,835.12
<p>Tanfer 97495749 'wp'</p> <p>23/6/20 @ 320 p.m 02 days</p> <p>P/P Resurvey before paint</p> <p>Tanfer @ 16 hours</p>				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.