

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 38545

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0442/2020/NS
Date : 22-Jun-20

Xiao Chen.

A4D1-H4.

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Kenneth Chue Soon Seng
Address : 18 Jalan Keris
Singapore 457552
Telephone : HP +65 96666855
Type of Claim : Own Damage Claims
Policy No. : 2100284065-08
Vehicle No : **SKE 1226 C**
Model Code : Audi A4 1.8 TFSI MU 8K202
Model / Year : Dec-11
Engine No : CDH 157269
Chassis No : WAUZZZ8K3CA085757
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Jun-20
Place of Accident : Around Serangoon Road / Moonstone Lane Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Estimated Labour Charges for Accident SKE 1226 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	X
2	To remove front bumper and lhs front fender. To renew lhs front fender. To repair lhs front door. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,450.00	1000 ✓
3	To respray lhs front fender, lhs front door and lhs sill panel.	\$ 2,800.00	1650 ✓
4	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00	✓
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,082.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDA 8777 L

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT FENDER - LH <i>Dented</i>	\$ 932.00	✓ 745.20
2	FRONT FENDER ATTACHMENT PARTS <i>Repl</i>	\$ 54.00	XX
3	FRONT FENDER BRACKET - LH FRONT <i>Repl</i>	\$ 50.00	X
4	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH REAR <i>Repl</i>	\$ 46.00	XX
5	FRONT FENDER BRACE - LH LOWER <i>Repl</i>	\$ 112.00	X
6	WHEEL HOUSING LINER <i>Repl</i>	\$ 226.00	X
7	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Repl</i>	\$ 42.00	X
8	FRONT ALUMINIUM RIM - LH <i>Int</i>	\$ 660.00	✓ 527.60
9	FRONT FENDER STONE CHIP COVER - LH <i>Repl</i>	\$ 14.00	✓ 11.28
10	SUNDRIES <i>Repl + New</i>	\$ 200.00	✓ 15.36 ✓
TOTAL SPARE PARTS CHARGES		: \$ 2,336.00	
TOTAL LABOUR CHARGES		: \$ 6,082.00	
GRAND TOTAL		: <u>\$ 8,418.00</u>	

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan
Surveyed Date : 24/06/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days.
04 Days.
R.S.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant