

Not Authored
61 Sep & 1600h

Trans-cab Auto Services Pte Ltd

AAD2006-049

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 678D

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

22 JUN 2020

SHD 678D

WDD2120012B221528

MERCEDES BENZ

E 220 BLUETEC

18.6.2020

CHINA TAIPING

16-12-15

	PART	LIST	
1	Rear Bumper	1310.00	\$ 3,105.00
1	Rear Bumper Lower		\$ 1,080.00
1	Rear Bumper Centre Pad		\$ 307.83
1	Rear Bumper Side Pad		\$ 186.33
1	Rear Bumper Tow Hook Cover		\$ 63.00
1	Rear LH Bumper Bracket		\$ 66.50
1	Rear RH Bumper Bracket		\$ 66.50
1	Rear Bumper Inner Frame		\$ 297.00
1	Rear Bumper Bottom Bracket LH		\$ 68.80
1	Rear Bumper Bottom Bracket RH		\$ 68.80
1	Rear Bumper Top Bracket		\$ 129.00
1	Rear Bumper Inner Bracket LH		\$ 198.00
1	Rear Bumper Inner Bracket RH		\$ 198.00
1	Rear Bumper Beam		\$ 1,215.00
1	Rear Bumper Beam Bracket LH		\$ 307.50
1	Rear Bumper Beam Bracket RH		\$ 307.50
1	Rear Bumper Bracket Centre		\$ 461.75
1	Rear Bumper Mounting Support Bracket		\$ 480.50
1	Rear Bumper Retainer Bracket Guide Rail LH		\$ 202.50
1	Rear Bumper Retainer Bracket Guide Rail RH		\$ 202.50
1	Rear Bumper Moulding		\$ 205.70
1	Bootlid		\$ 4,140.00
1	Bootlid 'E220' Badge		\$ 153.00
1	Bootlid 'BLUETEC' Badge		\$ 153.00
1	Bootlid Centre Logo Badge		\$ 153.00

Trans-cab Auto Services Pte Ltd

AAD2006-049

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 678D

1	Bootlid Protector Garnish With Chrome	\$	SL	732.00	}
1	Bootlid Weatherstrip	\$	SL	360.00	
1	Bootlid Lock - Top	\$	SL	300.00	
1	Bootlid Lock - Bottom	\$	SL	216.00	
1	Bootlid Lock Actuator	\$	SL	420.00	
1	Bootlid Weatherstrip	\$	SL	240.00	
1	Bootlid Motor Drive Unit Cover	\$	SL	210.00	
1	Boot Hinge Cable Duct Cover RH	\$	SL	185.60	
1	Boot Hinge Cable Duct Cover LH	\$	SL	185.60	
1	Bootlid Handle Trim Molding	\$	SL	340.00	
1	Bootlid Interior Trim Lamp	\$	SL	145.00	
1	Rear End Panel Outer	\$	N	1,971.00	
1	Rear End Panel Inner	\$	N	324.00	
1	Rear End Panel Inner Trim	\$	SL	630.00	
1	Rear End Panel Inner Trim Flap	\$	SL	360.00	
1	Rear Lamp RH	\$	SL	1,170.00	
1	Rear Lamp Panel Outer RH	\$	N	382.95	
1	Rear Lamp LH	\$	SL	1,170.00	
1	Rear Lamp Panel Outer LH	\$	N	382.95	
1	Rear LH Trunk Lid Lamp	\$	SL	1,190.00	
1	Rear RH Trunk Lid Lamp	\$	SL	1,190.00	
Total		\$		25,921.81	
10%		\$		2,592.18	
		\$		23,329.62	

Special Nett

1SET	Rear Bumper Parking Sensor	\$	Su	1,200.00	X
1SET	Bootlid Inner Trim Clip	\$	na	90.00	X
1SET	Rear End Panel Inner Trim Clip	\$	na	90.00	X
1SET	Rear Bumper Fastener Clip	\$	na	101.54	✓
1SET	Licence plate With Holder	\$	Su	225.00	X
1	Tyre Mechanical Jack	\$	Su	605.48	X
1	Tyre Mechanical Jack Holder Bracket	\$	Su	177.98	X

Trans-cab Auto Services Pte Ltd

AAD2006-049

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 678D

1 Boot Chrome Molding Clip	\$	nn	55.00	X
1 Rear Lamp Clip LH	\$	nn	45.00	X
1 Rear Lamp Clip RH	\$	nn	45.00	X
1SET Rear Bumper Lower Clip	\$	nn	90.00	X
1SET Rear Bumper Bracket Clip	\$	nn	85.00	X
1SET Rear Bumper Protector	\$	Nec nn	120.00	30sn

TOTAL \$ 2,929.99**GRAND TOTAL \$ 26,259.62****LABOUR**

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 6,500.00 2201

To Rust-Proofing Of The Affected Areas.

\$ nn 170.00 X

To Check Electrical Lighting Concerned.

\$ nn 120.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 6,500.00 2501

To Remove And Refit Interior Fittings, Trimings,
Garnish, Fittings And Other, to Enable Repair.

\$ 270.00 X

To Transfer Of Bootlid Fittings, Attachments And
Perform Water Seepage Test.

\$ 170.00 X

To Transfer Of Tire, Rim And On Wheel Balancing.

\$ 170.00 X

To Transfer Of Bumper Fittings, Attachments And
Perform Water Seepage Test.

\$ 170.00 X

Trans-cab Auto Services Pte Ltd

AAD2006-049

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 678D

To Transfer Of End Panel Fittings, Attachments And
Perform Water Seepage Test.

\$ *nn* 170.00 X

To Reinstall Rear Bumper Parking Sensor.

\$ 170.00 *601*

To Reseal Sealant On Gap

\$ *nn* 170.00 X**TOTAL \$ 14,580.00****Over All Total \$ 40,839.62****(Lump Sum) Repair Days**~~20 DAYS~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: