

Not Authorized
 61 Samp & 1600k

Trans-cab Auto Services Pte Ltd

AAD2006-049

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 678D

Vehicle No.:
 Chassis No.: **22 JUN 2020**
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD 678D
 WDD2120012B221528
 MERCEDES BENZ
 E 220 BLUETEC
 18.6.2020
CHINA TAIPING
 16-12-15

	PART	LIST	
1	Rear Bumper	<i>1510.00</i>	\$ <i>Bulldoz</i> 3,105.00
1	Rear Bumper Lower		\$ <i>Sn</i> 1,080.00
1	Rear Bumper Centre Pad		\$ <i>Sn</i> 307.83
1	Rear Bumper Side Pad		\$ <i>Sn</i> 186.33
1	Rear Bumper Tow Hook Cover		\$ <i>Sn</i> 63.00
1	Rear LH Bumper Bracket		\$ <i>Sn</i> 66.50
1	Rear RH Bumper Bracket		\$ <i>Sn</i> 66.50
1	Rear Bumper Inner Frame		\$ <i>Sn</i> 297.00
1	Rear Bumper Bottom Bracket LH		\$ <i>R</i> 68.80
1	Rear Bumper Bottom Bracket RH		\$ <i>R</i> 68.80
1	Rear Bumper Top Bracket		\$ <i>Sn</i> 129.00
1	Rear Bumper Inner Bracket LH		\$ <i>R</i> 198.00
1	Rear Bumper Inner Bracket RH		\$ <i>R</i> 198.00
1	Rear Bumper Beam		\$ <i>R</i> 1,215.00
1	Rear Bumper Beam Bracket LH		\$ <i>R</i> 307.50
1	Rear Bumper Beam Bracket RH		\$ <i>R</i> 307.50
1	Rear Bumper Bracket Centre		\$ <i>Sn</i> 461.75
1	Rear Bumper Mounting Support Bracket		\$ <i>Sn</i> 480.50
1	Rear Bumper Retainer Bracket Guide Rail LH		\$ <i>Sn</i> 202.50
1	Rear Bumper Retainer Bracket Guide Rail RH		\$ <i>Sn</i> 202.50
1	Rear Bumper Moulding		\$ <i>Sn</i> 205.70
1	Bootlid		\$ <i>R</i> 4,140.00
1	Bootlid 'E220' Badge		\$ <i>un</i> 153.00
1	Bootlid 'BLUETEC' Badge		\$ <i>un</i> 153.00
1	Bootlid Centre Logo Badge		\$ <i>un</i> 153.00

Trans-cab Auto Services Pte Ltd

AAD2006-049

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 678D

1	Bootlid Protector Garnish With Chrome	\$	Su	732.00	}	X
1	Bootlid Weatherstrip	\$	Su	360.00		
1	Bootlid Lock - Top	\$	Su	300.00		
1	Bootlid Lock - Bottom	\$	Su	216.00		
1	Bootlid Lock Actuator	\$	Su	420.00		
1	Bootlid Weatherstrip	\$	Su	240.00		
1	Bootlid Motor Drive Unit Cover	\$	Su	210.00		
1	Boot Hinge Cable Duct Cover RH	\$	Su	185.60		
1	Boot Hinge Cable Duct Cover LH	\$	Su	185.60		
1	Bootlid Handle Trim Molding	\$	Su	340.00		
1	Bootlid Interior Trim Lamp	\$	Su	145.00		
1	Rear End Panel Outer	\$	N	1,971.00		
1	Rear End Panel Inner	\$	N	324.00		
1	Rear End Panel Inner Trim	\$	Su	630.00		
1	Rear End Panel Inner Trim Flap	\$	Su	360.00		
1	Rear Lamp RH	\$	Su	1,170.00		
1	Rear Lamp Panel Outer RH	\$	N	382.95		
1	Rear Lamp LH	\$	Su	1,170.00		
1	Rear Lamp Panel Outer LH	\$	N	382.95		
1	Rear LH Trunk Lid Lamp	\$	Su	1,190.00		
1	Rear RH Trunk Lid Lamp	\$	Su	1,190.00		
Total		\$		25,921.81		
10%		\$		2,592.18		
		\$		23,329.62		

Special Nett

1SET	Rear Bumper Parking Sensor	\$	Su	1,200.00	X
1SET	Bootlid Inner Trim Clip	\$	na	90.00	X
1SET	Rear End Panel Inner Trim Clip	\$	na	90.00	X
1SET	Rear Bumper Fastener Clip	\$	na	101.54	✓
1SET	Licence plate With Holder	\$	Su	225.00	X
1	Tyre Mechanical Jack	\$	Su	605.48	X
1	Tyre Mechanical Jack Holder Bracket	\$	Su	177.98	X

Trans-cab Auto Services Pte Ltd

AAD2006-049

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 678D

1 Boot Chrome Molding Clip	\$	nn	55.00	X
1 Rear Lamp Clip LH	\$	nn	45.00	X
1 Rear Lamp Clip RH	\$	nn	45.00	X
1SET Rear Bumper Lower Clip	\$	nn	90.00	X
1SET Rear Bumper Bracket Clip	\$	nn	85.00	X
1SET Rear Bumper Protector	\$	nn	120.00	305n
TOTAL	\$		2,929.99	
GRAND TOTAL	\$		26,259.62	

LABOUR

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,500.00	220
To Rust-Proofing Of The Affected Areas.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$	nn	120.00	X
Putty And Spray Painting Of The Affected Portion.	\$		6,500.00	250
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, to Enable Repair.	\$	↪	270.00	X
To Transfer Of Bootlid Fittings, Attachments And Perform Water Seepage Test.	\$	↪	170.00	X
To Transfer Of Tire, Rim And On Wheel Balancing.	\$	↪	170.00	X
To Transfer Of Bumper Fittings, Attachments And Perform Water Seepage Test.	\$	↪	170.00	X

Trans-cab Auto Services Pte Ltd

AAD2006-049

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 678D

To Transfer Of End Panel Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00	X
To Reinstall Rear Bumper Parking Sensor.	\$	170.00	<i>601</i>
To Reseal Sealant On Gap	\$	<i>nn</i> 170.00	X
TOTAL	\$	14,580.00	
Over All Total	\$	40,839.62	

(Lump Sum) Repair Days ~~20 DAYS~~

2 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: